Environmental Monitor Construction Site Inspection Report MassDOT Project #608164 Construction Contract # 119678 EM Report #39

Project Description: Bruce Freeman Rail Trail Right-of-Way

Permit Description(s): Order of Conditions (MGL Chapter 131, Section 40 and 310 CMR 10.00, Mass DEP File No. 301-1362); 2022 EPA NPDES General Permit for Discharges from Construction Areas; U.S. Army Corps of Engineers Permit No NAE-2021-01975.

I. General Project Information

Project Name:	Bruce Freeman Rail Trail - Phase 2d - Sudbury			
Date of Inspections:	ttions: 12/20/2024			
Bi Weekly/ Monthly Period Covered:	eekly/ Monthly Period Covered: December Weekly Inspection #4			
Inspector's Name(s):	Anna Haznar			
Inspectors' Contact Information:	ahaznar@beta-inc.com			

II. Weather Information						
	Inspection #1	Inspection #2	Inspection #3	Inspection #4	Inspection #5	Inspection #6
	Inspector: Anna Haznar	Inspector: Anna Haznar	Inspector: Anna Haznar	Inspector: Anna Haznar	Inspector:	Inspector:
<u>WeatherUnderground</u>	12/2/2024	12/6/2024	12/12/2024	12/20/2024	орессо	spector.
Type of Inspection (i.e. non-storm event, pre- storm event, during-storm event or post- storm event):	Post-storm	Non-storm	Post-storm	Post-storm		
Number of days since last rain event greater than .25"	4		1	1		
Has there been a storm event since the last inspection?	Yes		Yes	Yes		
If yes, please provide storm start date, storm duration, and approx amount of						
Storm 1:	November 28th (14 hours 1.7")		December 11th (11 hours 1.94")	December 18th (5 hours 0.6")		
Storm 2:				December 19th (4 hours 0.52")		
Storm 3:						
Storm 4:						
Weather at the time of inspection (i.e. clear, overcast, cloudy, rain, sleet, fog, snow,	Clear	Clear	Clear	Overcast		
Temperature:	34	32	40	31		
Unusual Conditions (drought, severe storm):						
Have any discharges occurred since the last inspection report?	No	No	No	Yes		
If yes, please describe:						
				Erosion of exposed soils has resulted in a discharge to the stream at Station 216+50		

Note: Inspections should only be conducted on days during work hours while RE or ARE is onsite. The EM should contact the RE to address any immediate corrective actions.

III. General Description of Construction Status

12/2/2024 - At the time of the Site visit, no work was occurring.

12/6/2024 - At the time of the Site visit, no work was occurring.

12/12/2024 - At the time of the Site visit, work was occurring on the utility box and traffic lights adjacent to the Hudson Road intersection.

12/20/2024 - At the time of the Site visit, no work was occurring.

	IV. Status of Existing BMPs							
Control Measure (These are examples; list measures specific to the project)	Cleaning or Repair Needed (yes no n/a)	Comments/Recommendations from the EM						
Perimeter Controls	Yes	Perimeter erosion and sedimentation control measures were installed at the commencement of the Project and are in varying conditions across the Site; however, they were generally observed to be degraded. Perimeter controls were generally in degraded condition along culverts, streams, and cattle crossings. New perimeter controls were added on 6/27/2024 at Stations 310+00 through 311+00 as requested. New erosion controls have been installed between the path and the crushed stone shoulders at Station 216+00 to 217+50. Areas that still require stabilization do not appear to be at risk for erosion due to surrounding vegetation upgradient of Resource Areas.						
Inlet Protection Measures	No							
Stabilized Construction Entrances	No							
Stockpile Protections	No							
Dust Control	No							
Street Sweeping	Yes	Crushed stone was observed on the path throughout the Project in varying volumes.						
Dewatering Controls	No							
Construction Equipment and Material Storage	No							
Construction and Domestic Waste Storage and Collection	No							
Location of Sanitary Waste Facilities	No							
Washout Areas	No							
Fertilizers, Herbicides, and Landscape	N/A							
Stabilization of Exposed Soil	Yes	Varying degrees of stabilization are present within areas that were constructed/graded as part of the Project. Seed has been applied to multiple locations of exposed soil throughout the path. Erosion control blankets have been installed on the slope near Station 165+00 to 167+00 and Station 217+45. Loam that was applied to the streambank at Station 215+00 to 217+00 requires further stabilization, and erosion has been actively occurring. Due to the time of year, non-vegetative stabilization (i.e. erosion control netting) is recommended.						
Overall Adherence to Environmental Permits	Yes	As noted in Action Items 41 and 42, it appears that work has been conducted beyond the limits of work approved under the Order of Conditions. These areas will require coordination amongst the Project Team to confirm if any restoration is required. A Site walk was conducted with BETA staff, MassDOT staff and the Conservation Agent on 11/19/2024 to discuss potential resolutions for compliance issues.						
	Note	: Use station numbers, wetland ID or other means to determine locations of BMP's that need repairs.						

V. Compliance Table - Compliance Action Items

V. 1. Compliance Action Items Observed During the One Month Reporting Period Ending [December 31, 2024].

Current Open and Closed Compliance Action Items Observed During the Reporting Period Ending [June 30, 2024]. For those items within the most current two week period, color the Item in blue, as shown on lines 48-50 as an example. RED text indicates that the item is outstanding. Once item is resolved, place resolution date in 'Recommended Resolution/Resolution Date' column, convert to BLACK text, and move to the bottom of the Action Item list. Place resolution date on TOP of resolution action. Each Compliance Action Item is assigned a unique number only to be used to reference that item for the duration of the project. Separate but related Action Items will be labeled in an "Item Number-1 and Item Number-2" manner or similar. Completed action items can be removed once they have appeared in the Bi-Weekly Report to MassDEP

"Urgent" - Needs to be completed immediately, "High" - Needs to be completed within 7 days and has short-term potential to impact resource areas, "Low" - Needs to be completed within 7 days with minimal potential to impact resource areas

Ite	n Location/ Description	Observation Date	Resolution Due Date	Recommended Resolution / Resolution Date	Comments/Updates
62	Loam and seed was applied to the streambank at Station 216+00 to 217+00 and requires further stabilization Priority: High	11/25/2024	12/2/2024	An erosion control blanket should be installed along this slope.	12/2/2024 - Loam and seed have been applied to the streambank at Station 215+00. Stabilization is required at Stations 215+00 to 217+00. 12/6/2024 - Observation remains. See previous update. 12/12/2024 - Observation remains. Rill erosion was observed within the loam applied to this area from Station 215+00 to 216+00. 12/20/2024 - Observation remains. Loam has begun to erode, resulting in a discharge to the stream at Station 216+50.
53	Stone was observed requiring removal from the swale on the east side of the trail at Station 172+00 to 173+00 Priority: High	7/29/2024	8/6/2024	Remove stone from the swale.	8/5/2024 - Observation remains. 8/7/2024 - Observation remains. 8/12/2024 - Observation remains. Material was observed to have migrated within the swale to Station 173+50. 8/16/2024 - Stone is still present within the swale. 8/20/2024 - Observation remains. Crushed stone has migrated further down the swale to Station 171+50. 8/16/2024 - Observation remains. Stone is still present within the swale. 9/3/2024 - Observation remains. 9/10/2024 - Observation remains. Stone is still present within the swale. 9/16/2024 - Observation remains. The contractor indicated that the stone within the swale would be hand removed. 9/23/2024 - Observation remains. The contractor indicated that the stone within the swale would be hand removed. 9/23/2024 - Observation remains. It appears as though some stone has migrated further south down the swale. 10/4/2024 - Observation remains. Stone is still present within the swale. 10/8/2024 - Observation remains. 10/15/2024 - Observation remains. 10/15/2024 - Observation remains. Stone is covered with vegetation in some areas. 10/22/2024 - Observation remains. 11/2/2024 - Observation remains. 11/12/2024 - Observation remains. 11/12/2024 - Leaf litter has completely covered the stone in this location. The Contractor should indicate if stone has been removed from this location. 11/19/2024 - See previous update. 11/12/2024 - See previous update. 11/22/2024 - Observation remains. Stone is still present within the swale and requires removal. Leaf litter is currently covering a majority of the stone. 12/2/2024 - Observation remains. Stone is present within the swale under leaf litter. 12/6/2024 - Observation remains. Stone is present within the swale under the leaf litter.

47	Slope stabilization required due to condition of compost filter tubes at Station 265+50 and 273+00 Priority: High	6/7/2024	6/14/2024	Stabilize the slope with the approved seed mixture and provide interim stabilization such as straw mulch.	6/14/2024 - Observation remains. 6/17/2024 - Observation remains. 6/24/2024 - Observation remains. 6/27/2024 - Observation remains. 7/8/2024 - Observation remains. 7/8/2024 - Observation remains. 7/29/2024 - Observation remains. 7/29/2024 - Observation remains. 7/29/2024 - Observation remains. 8/7/20204 - Observation remains. 8/7/2024 - Regrowth of vegetation has been observed in this area. This item will remain open until the area is fully stabilized. 8/12/2024 - Observation remains. 8/12/2024 - Observation remains. 8/16/2024 - Observation remains. 8/16/2024 - Observation remains. 8/20/2024 - Observation remains. 8/20/2024 - Observation remains. 8/20/2024 - Observation remains. 9/3/2024 - Observation remains. 9/3/2024 - Observation remains. 9/3/2024 - Observation remains. 9/16/2024 - Observation remains. 9/16/2024 - Observation remains. 9/27/2024 - Observation remains. 9/27/2024 - Observation remains. 9/27/2024 - Observation remains. 9/27/2024 - Observation remains. The contractor indicated hydroseed will be applied here soon. 10/4/2024 - Observation remains. Hydroseed has not been applied to this area. 10/4/2024 - Observation remains. Hydroseed has not been applied to this area. 10/4/2024 - Observation remains. No germination has been observed. 10/29/2024 - Observation remains. See previous update. 11/5/2024 - Observation remains. Some germination has been observed but the area is not considered stabilized. 11/12/2024 - Observation remains. See previous update. 11/2/2024 - Observation remains. 12/2/2024 - Observation remains.
----	---	----------	-----------	---	--

Sediment is eroding downhill from behind the cemental storement of the service of the section that is currently unwegetated. Apply seed and temporarily stabilized measures are recommended on the section that is currently unwegetated. 8/18/2024 Observation remains. 8/27/2024 Observation remains. \$7/27/2024 Observation remains. \$7/27/2024 Observation remains. \$7/27/2024 Observation remains. \$7/27/2024 Observation remains. See update from 9/3/2024. 9/3/2024 Observation remains. No germination has been observed in this location. 9/3/2024 Observation remains. No germination has been observed in this location. 9/3/2024 Observation remains. No germination has been observed in this location. 9/3/2024 Observation remains. No germination has been observed in this location. 9/3/2024 Observation remains. No germination has been observed in this location. 9/3/2024 Observation remains. No germination has been observed in this location. 9/3/2024 Observation remains. No germination has been observed in this location. 9/3/2024 Observation remains. No germination has been observed in this location. 9/3/2024 Observation remains. No germination has been observed in this location. 9/3/2024 Observation remains. No germination has been observed in this location. 9/3/2024 Observation remains. See update from this location. 9/3/2024 Observation remains. No germination has been observed in this location
--

Soil and organic debris has been placed within the wetland between wetland flagging WF#23-119 and WF#23-118 at Station 224+00 Priority: High	5/28/2024	Remove all material and provide stabilization of the area with the approved wetland seed mixture. Straw should also be placed for interim stabilization.	5/28/2024 - Observation remains. 6/17/2024 - Observation remains. 6/17/2024 - Observation remains. 6/17/2024 - This area has been hydroseeded multiple times, but the debris should also be removed from the downgradient wetland. 6/17/2024 - This area has been hydroseeded multiple times, but the debris should also be removed from the downgradient wetland. 6/24/2024 - Observation remains. 6/24/2024 - Observation remains. The area was hydroseeded again. 7/8/2024 - Germination was observed and the area will be monitored for stabilization. 7/15/2024 - Observation was observed and the area will be monitored for stabilization. 7/15/2024 - Observation remains. 8/5/2024 - Observation remains. 8/5/2024 - Observation remains. 8/5/2024 - Observation remains. 8/7/2024 - Regrowth of vegetation has been observed in this area. This item will remain open until the area is fully stabilized. Debris is still present in wetland and requires removal. 8/12/2024 - Observation remains. 8/16/2024 - Observation remains. 8/16/2024 - Observation remains. 8/20/2024 - Observation remains. 9/3/2024 - Observation remains. 9/3/2024 - Observation remains. 9/16/2024 - Observation remains. 9/16/2024 - Observation remains. 9/16/2024 - Observation remains. Flydroseed has not been applied to this area. 10/4/2024 - Observation remains. Hydroseed has not been applied to this area. 10/4/2024 - Observation remains. Hydroseed has not been applied to this area. 10/15/2024 - Observation remains. Hydroseed has not been applied to this area. 10/15/2024 - Observation remains. Hydroseed has not been applied to this area. 10/12/2024 - Observation remains. Hydroseed has not been applied to this area. 10/12/2024 - Observation remains. Hydroseed has not been applied to this area. 11/12/2024 - Observation remains. Hydroseed has not been applied to this area. 11/12/2024 - Observation remains. Hydroseed has not been applied to this area. 11/12/2024 - Observation remains. No germination has been observed in this area. 11/12/2024 - Observation remains. No germination has
--	-----------	--	---

6	Exposed sediment slope at Station 172+00 to 175+00 Priority: High	5/8/2024	5/15/2024	Install temporary sediment controls along the slope such as jute netting and/or straw following the application of seed.	5/16/2024 - Observation remains. 5/21/2024 - Observation remains. 5/21/2024 - Observation remains. 5/21/2024 - Observation remains. 6/3/2024 - See previous update. 6/3/2024 - Observation remains. 6/14/2024 - Observation remains. 6/24/2024 - Observation remains. 6/24/2024 - Observation remains. 6/24/2024 - Observation remains. 6/24/2024 - Observation is still required. 7/8/2024 - Inter earthwork has been regraded and loam has been spread. New trees have been planted upgradient of the swales. Stabilization is still required. 7/8/2024 - Interecting has been installed over the applied seed, and the area will be monitored for germination. 7/15/2024 - See previous update. 7/22/2024 - Observation remains. 8/2/2024 - Observation remains. 8/3/2024 - Observation remains. 9/3/2024 - Observation remains. 9/3/2024 - Observation remains. 9/3/2024 - Observation remains. 9/3/2024 - Observation remains. See place and application of the approved seed mixture is required at this location. 9/3/2024 - Observation remains. See place and application of the approved seed mixture is required at this location. 9/3/2024 - Observation remains. See place and application of the approved seed mixture is required at this location. 9/3/2024 - Observation remains. See place from 10/4/2024. 9/3/2024 - Observation remains. See update from 10/4/2024. 10/3/2024 - Observation remains. See update from 10/4/2024. 10/3/2024 - Observation remains. See updat
---	---	----------	-----------	--	--

43	Overtopped compost filter tubes and exposed soils beyond the limits of work at Station 105+00 Priority: High	6/7/2024		Stabilize the area with the approved seed mixture and provide interim stabilization such as straw mulch.	6/14/2024 - Observation remains. 6/14/2024 - Observation remains. 6/24/2024 - Observation remains. 6/24/2024 - Observation remains. 7/15/2024 - Observation remains. 7/15/2024 - Observation remains. 7/22/2024 - Observation remains. 7/22/2024 - Observation remains. 7/29/2024 - Observation remains. 8/5/2024 - Observation remains. 8/5/2024 - Observation remains. 8/1/2024 - Observation remains. 9/12/2024 - Observation remains. 9/12/2024 - Observation remains. 9/12/2024 - Observation remains. 9/10/2024 - Observation remains. 9/23/2024 - Observation remains. 9/23/2024 - Observation remains. 10/4/2024 - Hydroseed has been applied here; however, the contractor should provide an update on long-term slope stabilization plans. 10/4/2024 - Observation remains. Germination has not been observed. 10/15/2024 - Observation remains. Germination has not been observed but the area is not considered stabilized. 10/29/2024 - Observation remains. Some germination has been observed but the area is not considered stabilized. 10/29/2024 - Observation remains. Some germination has been observed but the area is not considered stabilized. 11/2/2024 - Observation remains. Soed has stabilized the area. 11/12/2024 - Observation remains. See pudate from 11/19/2024. 11/12/2024 - Observation remains. See previous update. 11/12/2024 - Observation remains. See update from 11/19/2024. 12/2/2024 - Observation remains. See update from 11/19/2024.
----	--	----------	--	--	--

V.2. On Going (Longer-Term) Compliance Items

Typically, these items require coordination with MassDEP. If so, remove once approval is obtained from MassDEP


Item	Location/ Description	Observation Date	Resolution Due Date	Recommended/Discussed Resolution	Comments/Updates
61	Invasive vegetation including Japanese knotweed (Reynoutria japonica), bittersweet (Celastrus orbiculatus), bush honeysuckle (Lonicera spp.), burning bush (Euonymus alatus), purple loosestrife (Lythrum salicaria), glossy buckthorn (Frangula alnus) and garlic mustard (Alliaria petiolata) have been observed throughout the path. Priority: High	10/22/2024	10/29/2024	Invasive Species should be removed by manual and/or chemical removal methods	10/29/2024 - Invasive species are present throughout the trail both within upland and Resource Areas. Populations of glossy buckthorn and purple loosestrife are present within the wetland replication area. 11/5/2024 - Observation remains. See update from 10/29/2024. 11/12/2024 - Observation remains. Invasive species are still present throughout the trail. Some invasives have been observed with no leaves due to winter die back. 11/19/2024 - Observation remains. Further invasive species management will be required during the next growing season. 11/22/2024 - Observation remains. 11/25/2024 - Observation remains. 12/6/2024 - Observation remains. This action item has been moved to the Long-Term Compliance Items section because it can only be resolved during the next growing season. 12/12/2024 - Observation remains.
57-1	Japanese hops (<i>Humulus japonicus</i>) has been observed throughout the Project and requires removal Priority: High	10/22/2024	10/29/2024	The Contractor should manage remaining Japanese hops by hand pulling and the application of herbicide.	10/22/2024 - This Action Item has been reopened due to observations of both dead and living Japanese hops in select locations along the Project. BETA and MassDOT will coordinate further with the Sudbury Conservation Agent to clarify the extents of remaining living vegetation as removal efforts progress. 10/29/2024 - Plants that were observed as alive along Route 117 during the last inspection were observed to be wilting due to winter die back. 11/5/2024 - Observation remains. See update from 10/29/2024. 11/12/2024 - See update from 10/29/2024. 11/19/2024 - Observation remains. See update from 10/29/2024. Management of Japanese hops should occur during the next growing season. 11/22/2024 - Observation remains. 11/25/2024 - Observation remains. 12/2/2024 - Observation remains. 12/6/2024 - Observation remains. This action item has been moved to the Long-Term Compliance Items section because it can only be resolved during the next growing season. 12/12/2024 - Observation remains.


59	Multiple locations of exposed soils along the Project corridor require stabilization Priority: High	9/3/2024	9/10/2024	The contactor should apply the approved seed mixture to areas of exposed soils and place straw.	9/3/2024 - Herbicide application caused multiple areas along the path to be no longer stabilized. If thatch is present in these locations the thatch should be removed before seeding occurs. A location near Station 320+50 has been cleared outside of the limit of work and requires stabilization. Other areas along the path where seed did not germinate should be reseeded with the approved seed mix and straw should be placed on the areas of exposed soil. 9/10/2024 - Observation remains, see previous update. A few locations along the trail have been hydroseeded but a majority of the locations of exposed soil require seed and stabilization. 9/16/2024 - Observation remains. The contactor indicated areas of bare soil will be hydroseeded. 9/23/2024 - Observation remains. It does not appear as though any hydroseeding has been done since the last inspection. Areas throughout the trail require removal of thatch and application of seed for stabilization. 9/21/2024 - Observation remains. The contractor reached out and indicated all areas of exposed soils south of Hudson Road were not seeded using hydroseed; hydroseed was applied in a few locations, but there are still large areas of exposed soil both south and north of Hudson Road that require seeding. That has not removed in any areas before hydroseed was applied. The contractor should provide the tag from the seed mix that was used to the Conservation Commission to ensure that the required native seed mix was used to the Conservation Commission to ensure that the required native seed mix was used to the Conservation and the form 10/4/2024. No additional hydroseed has been applied since the last inspection. No germination has been observed in areas where hydroseed was applied. 10/23/2024 - Observation remains. See update from 10/4/2024. No additional hydroseed has been applied since the last inspection. No germination has been observed in a few locations where hydroseed has been applied since the last inspection. Sone germination has been observed in a few locations where
----	---	----------	-----------	---	--


Crushed stone used for the dense graded crush stone shoulders has been observed as migrating both onto the path, off the sides of the path, and into the adjacent Resource Areas throughout the Project Priority: High	8/14/2024	Remove all crushed stone from Resource Areas and develop a plan to cease discharges of stone.	8/12/2024 - Crushed stone is still present in varying amounts throughout the path and on the sides of the path. 8/16/2024 - Observation remains. 8/20/2024 - Crushed stone has been removed from some adjacent resource areas but is still observed as migrating onto and off of the path in multiple locations throughout the Project. 8/27/2024 - Crushed stone has been observed as migrating both onto the path and off the side of the path in multiple locations. Stone was observed as migrating both onto the path and off the side of the path in multiple locations. Stone was observed to have discharged to the cattle crossing at Station 190-50 and within the streambed at Station 215-00 to 216-00. Crushed stone was observed to have been placed on the root system of a fallen tree at Station 310-00 near Bank flag #84-108. 9/10/2024 - Observation remains. Crushed stone is still present within the cattle crossing, the streambed, and on the root system of the fallen tree. Crushed stone continues to migrate on to and off of the path. 9/16/2024 - Observation remains. The contractor indicated the locations where crushed stone has migrated off the path will be hand removed and crushed stone will be swept off the path prior to the opening of the trail. 9/23/2024 - Observation remains. It does not appear as though crushed stone has migrated onto or flof the path has been removed in any location along the Project. More crushed stone has migrated onto the path in varying amounts. 9/27/2024 - Observation remains. Crushed stone is still present in multiple locations on and off the sides of the path in varying amounts. 9/18/2024 - Observation remains. Crushed stone is still present in multiple locations on and off the sides of the path. 9/18/2024 - Observation remains. Crushed stone is still present in multiple locations on and off the sides of the path. 9/18/2024 - Observation remains. Crushed stone is still present in multiple locations on and off the sides of the path. 9/18/2024 - Observation remains. Crushed stone is still present in mul
---	-----------	---	--


42	Riprap slope extends beyond limits of work along the WF1 Series wetland near flags 103 to 107 Priority: High	5/28/2024	6/4/2024	The Contractor should confirm if this work was permitted by the Conservation Commission, as it does not appear to be a part of the approved plans/impacts. MassDOT should be consulted on next steps regarding notification and potential restoration.	5/31/2024 - Observation remains. 6/7/2024 - Observation remains. 6/7/2024 - Observation remains. 6/14/2024 - Riprap slope has been altered and active construction is repairing the area. 6/14/2024 - During this inspection, additional work in support of the repair/potential replacement of an underlying pipe has was ongoing, it is recommended that the contractor confirm that they have coordinated with the Conservation Commission for this work and provide a restoration plan for the area once work is complete. 6/24/2024 - During this inspection, BETA was informed that the existing cast iron pipe was replaced with a new concrete 12-inch reinforced reinf
----	--	-----------	----------	--	--


41	Stream Bank has been regraded beyond the limit of work at Station 216+00 Priority: High	5/28/2024	6/4/2024 VI. Agency Suhmittals	The Contractor should confirm if this work was permitted by the Conservation Commission, as it does not appear to be a part of the approved plans/impacts. MassDOT should be consulted on next steps regarding notification and potential restoration.	5/31/2024 - Observation remains. 6/14/2024 - Observation remains. 6/14/2024 - Observation remains. 6/14/2024 - Observation remains. 6/24/2024 - Observation remains. 6/24/2024 - Observation remains. 6/24/2024 - Observation remains. 6/24/2024 - Observation remains. 7/8/2024 - Observation remains. 7/8/2024 - Observation remains. 7/15/2024 - This area could not be assessed due to paving operations ongoing during the inspection. 7/22/2024 - Crushed stone and sediment continue to be discharged to the stream between Stations 215+00 and 217+00 due to overtopped and undermined compost filter tubes. 7/29/2024 - Observation remains. 8/5/2024 - Observation remains. 8/5/2024 - Observation remains. 8/12/2024 - Observation remains. 8/12/2024 - Observation remains. 8/16/2024 - Observation remains. 8/20/2024 - Stone has been removed; however, additional alteration to Resource Areas beyond the limit of work continue. 8/27/2024 - Observation remains. 9/23/2024 - Observation remains. 9/3/2024 - Observation remains. 9/3/2024 - Observation remains. 9/3/2024 - Observation remains. 9/10/2024 - Observation remains. 10/8/2024 - Observation remains. 10/8/2024 - Observation remains. 10/8/2024 - Observation remains. 10/8/2024 - Observation remains. Stone is still present within the streambed at this location. 10/29/2024 - Observation remains. Stone is still present within the streambed at this location. 10/29/2024 - Observation remains. Stone is still present within the streambed at this location. 10/29/2024 - Observation remains. Stone is still present within the streambed at this location. 10/29/2024 - Observation remains. Stone is still present within the streambed at this location. 10/29/2024 - Observation remains. Stone is still present within the streambed at this location. 10/29/2024 - Observation remains. Stone is still present within the streambed at this location. 10/29/2024 - Observation remains. St				
	Submittal	Date Submitted	Description	(Note: only inica carrer menany	Status				
	VII. Attachments (#3 only attached with monthly report)								
			VIII. Attacimients (3 only accached with monthly rep					
	d Sketch		VII. Attachments (3 omy attached with monthly rep					
2. Pho	d Sketch otographic Documentation /eek Look ahead schedule		VII. Attacilinents (3 only accached with monthly rep	···				




























Site Location Bruce Freeman Rail Trail Right-of-Way

BETA Project No. 24.10326.23

Photo Date: No. 1 12/20

12/20/2024

Direction Photo Taken:

Toward the North

Description:

View of the overtopped compost filter tube beyond the limits of work at Station 105+00 per Compliance Action Item 43.



Photo No. 2 Date: 12/20/2024

Direction Photo Taken:

Toward the North

Description:

View of exposed soil Station 139+00 that requires stabilization per Long Term Compliance Action Item 59.





Site Location Bruce Freeman Rail Trail Right-of-Way

BETA Project No. 24.10326.23

Photo Date: No. 3

Date: 12/20/2024

Direction Photo Taken:

Toward the South

Description:

View of exposed soil Station 165+00 that requires stabilization per Long Term Compliance Action Item 59.



Photo No. 4

Date: 12/20/2024

Direction Photo Taken:

Toward the East

Description:

View of hydroseed with some germination along slopes at Station 172+00 to 175+00 per Compliance Action Item 6.





Site Location Bruce Freeman Rail Trail Right-of-Way

BETA Project No. 24.10326.23

Photo Date: No. 5 12/20

12/20/2024

Direction Photo Taken:

Toward the North

Description:

View of a location where hydroseed was recently applied with no observable germination and crushed stone that requires removal at Station 180+00 per Long Term Compliance Action Item 58 and 59

Photo Date: No. 6 12/20/2024

Direction Photo Taken:

Toward the South

Description:

View of loam that requires stabilization at Station 215+00 per Compliance Action Item 62. Note rill erosion is occurring in this area.







Site Location

Bruce Freeman Rail Trail Right-of-Way

BETA Project No. 24.10326.23

Photo No. 7 Date:

12/20/2024

Direction Photo Taken:

Toward the South

Description:

View of the location where loam that was placed on the streambank has eroded into the streambed at Station 216+50, resulting in a discharge per Compliance Action Item 62.



Photo No. 8

Date: 12/20/2024

Direction Photo Taken:

Toward the South

Description:

View of the location where the stream bank has been regraded beyond the limits of work and stabilization of loam is required at Station 216+00 per Long Term Compliance Action Item 41 and 62. Note rill erosion is occurring in this area.





Site Location

Bruce Freeman Rail Trail Right-of-Way

BETA Project No. 24.10326.23

Photo No. 9 Date:

12/20/2024

Direction Photo Taken:

Toward the West

Description:

View of loam that requires stabilization at Station 217+00 per Compliance Action Item 62.



Photo

Date:

No. 10 12/20/2024

Direction Photo Taken:

Toward the South

Description:

View of the slope where hydroseed was applied and some germination has occurred at Station 217+45 per Compliance Action Item 34.





Site Location

Bruce Freeman Rail Trail Right-of-Way

BETA Project No. 24.10326.23

Photo No. 11

Date: 12/20/2024

Direction Photo Taken:

Toward the North

Description:

View of an area of exposed soil at Station 297+50 per Long Term Compliance Action Item 59.



Photo No. 12

to Date: 12/20/2024

Direction Photo Taken:

Toward the Northwest

Description:

View of crushed stone that requires removal from the swale at Station 303+00 per Long Term Compliance Action Item 58.





Site Location

Bruce Freeman Rail Trail Right-of-Way

BETA Project No. 24.10326.23

Photo No. 13

Date:

12/20/2024

Direction Photo Taken:

Toward the North

Description:

View of placed loam that requires stabilization at Station 311+00 per Long Term Compliance Action Item 59.



Photo Date: No. 14 12/20

12/20/2024

Direction Photo Taken:

Toward the North

Description:

View of the riprap slope that extends beyond the limit of work along the WF1 Series wetland at Station 332+00 per Long Term Compliance Action Item 42.

