

**Town of Sudbury: Priority for
ADA Transition Plan - Parks**

Priorities:
Priority 1: Program Access* or Safety
Priority 2: Navigational Issue
Priority 3: Additional Access*
Priority 4: Enhanced Usability**

***Note:**
Some toilet rooms issues compromise Program Access.
Some toilet rooms with less central issues (e.g., partially accessible toilet rooms), fall under Additional Access.

****IHCD Cost Estimation Notes:**
- Cost of design is not included.
- Does not include costs when note indicates future work.
- Labor cannot be estimated for all remedies.
- There is no cost noted when it's presumed to be a maintenance issue.
- Cost based on a national average. Cost is not based on prevailing wage.
- There is no cost noted when it's presumed to be a maintenance issue. *Estimates are intended as a guide to budgeting access modifications and are not intended to be absolutely comprehensive or definitive.*

Information Provided by Institute for Human Centered Design											Status of Barrier Removal				
ID	Facility Name	Element	Issue/Physical Barrier	Location	Floor	Room	Town Priority	Priority for Barrier Removal	Remedies	Quantity	Estimated Cost of Barrier Removal	Barrier Removal Complete (Y/N)	Completion Date (Month/Year)	Completion Date (Fiscal Year)	
1	Broadacres Farm	A. Exterior Access Route	H. Running slope > 1:20 (5%) K. Surface is not stable, firm, and slip-resistant N. Accessible route not provided	Path Between Horse Riding Practice Building and Horse Barn	Exterior	N/A	Priority 1	Program Access	Ensure an accessible route is provided with a slope no greater than 1:20 (5.00%). (Cost estimate for a 250' long 4' wide stone dust walkway.)	1	\$8,000				
2	Broadacres Farm	A. Exterior Access Route	J. Level changes > 1/4"	House Entrance	Exterior	N/A	Priority 1	Program Access	Alter change in level to be 1/4" high max. (Cost estimate for a 4' by 4' asphalt area.)	1	\$160				
3	Broadacres Farm	A. Exterior Access Route	N. Accessible route not provided	Horse Riding Practice Building	Exterior	N/A	Priority 1	Program Access	Ensure an accessible route is provided to the new main entrance door. (Cost estimate for a 10' long 4' wide stone dust walkway.)	1	\$320				
4	Broadacres Farm	A. Exterior Access Route	N. Accessible route not provided	Kitchen Egress to Outdoor Office	Exterior	N/A	Priority 1	Program Access	Due to lack of space an accessible route may not be technically feasible to the outdoor office.	1	\$0				
5	Broadacres Farm	C. Off-Street Parking Lot or Garage	A. Total # of parking C. Total # of designated van accessible spaces	Parking Area	Exterior	N/A	Priority 1	Program Access	Provide one van accessible parking space.	1	\$1,850				
6	Broadacres Farm	E. Exterior Ramp	A. No lower handrail 18"-20" high provided B. Ramp < 48" wide G. Handrails do not extend 12" past top & bottom H. Handrails have non-compliant cross section Z. Ramp is not located on an accessible route	House - Main Entrance	Exterior	N/A	Priority 3	Additional Access	Rebuild ramp so that there is 48" inches clear. Provide a lower handrail between 18" to 20" high on each side. Provide handrails that extend horizontally above the landing for 12" min. beyond the top and bottom of ramp runs. Provide handrails with 1-1/4" to 1-1/2" circular cross sections. (Cost estimate for a new 30' pressure treated wood ramp.)	1	\$7,843				
7	Broadacres Farm	G. Entrance	B. Entrance not on an accessible route C. Directional sign to accessible entrance not provided	Horse Riding Practice Building Inaccessible Door	Exterior	N/A	Priority 1	Program Access	Provide a directional sign indicating the location of the nearest accessible entrance.	1	\$346				
8	Broadacres Farm	G. Entrance	B. Entrance not on an accessible route O. Threshold > 1/2" high Q. Hardware not operable with a closed fist D. International Symbol of Accessibility not provided	Horse Riding Practice Building Observation Area	Exterior	N/A	Priority 1	Program Access	After the entrance is made accessible, provide a sign with the International Symbol of Accessibility (ISA). Provide hardware that can be operable with one hand and not require tight grasping, pinching, or twisting of the wrist. Provide a sloped walkway with a 5' by 5' level platform at the door. (Cost estimate includes a 15' long concrete route to the door, door hardware and sign.)	1	\$2,030				
9	Broadacres Farm	G. Entrance	D. International Symbol of Accessibility not provided	Horse Riding Practice Building Main Entrance	Exterior	N/A	Priority 1	Program Access	Provide a sign with the International Symbol of Accessibility (ISA) at the new accessible entrance door.	1	\$346				
10	Broadacres Farm	G. Entrance	O. Threshold > 1/2" high Q. Hardware not operable with a closed fist	House - Main Entrance	Exterior	N/A	Priority 3	Additional Access	Alter threshold to be 1/2" high max. Provide hardware that can be operable with one hand and not require tight grasping, pinching, or twisting of the wrist.	1	\$634				
11	Broadacres Farm	G. Entrance	R. Door requires > 15 lbs. of force to open	Horse Riding Practice Building Main Entrance	Exterior	N/A	Priority 3	Additional Access	Provide an accessible door into the facility. (Cost estimate for installing a solid core wood door.)	1	\$2,972				

Information Provided by Institute for Human Centered Design											Status of Barrier Removal			
ID	Facility Name	Element	Issue/Physical Barrier	Location	Floor	Room	Town Priority	Priority for Barrier Removal	Remedies	Quantity	Estimated Cost of Barrier Removal	Barrier Removal Complete (Y/N)	Completion Date (Month/Year)	Completion Date (Fiscal Year)
12	Broadacres Farm	H. Emergency Exit	B. Tactile sign not provided at exit C. Directional sign to accessible emergency exit not provided	Kitchen Egress	1	N/A	Priority 2	Navigational Issue	Provide tactile exit signs with raised characters and braille at exit doors. Mount signs between 48"- 60" above the finished floor located on the latch side of the door. Provide a directional sign indicating the location of the nearest accessible emergency exit.	1	\$464			
13	Broadacres Farm	H. Emergency Exit	B. Tactile sign not provided at exit C. Directional sign to accessible emergency exit not provided	Horse Riding Practice Building Inaccessible Door	Exterior	N/A	Priority 2	Navigational Issue	At the interior of the exit door: provide tactile exit signs with raised characters and braille at exit doors. Mount signs between 48"- 60" above the finished floor located on the latch side of the door. Provide a directional sign indicating the location of the nearest accessible emergency exit.	1	\$464			
14	Broadacres Farm	H. Emergency Exit	B. Tactile sign not provided at exit D. Illuminated Int. Symbol of Acc. not provided (MAAB)	Horse Barn Exit	1	N/A	Priority 2	Navigational Issue	Provide tactile exit signs with raised characters and braille at exit doors. Mount signs between 48"- 60" above the finished floor located on the latch side of the door. Provide an illuminated sign with the International Symbol of Accessibility.	1	\$1,116			
15	Broadacres Farm	H. Emergency Exit	B. Tactile sign not provided at exit D. Illuminated Int. Symbol of Acc. not provided (MAAB)	Horse Riding Practice Building Observation Area	Exterior	N/A	Priority 2	Navigational Issue	Provide a tactile exit signs with raised characters and braille at the interior. Mount signs between 48"- 60" above the finished floor located on the latch side of the door. After the door is made accessible, provide an illuminated sign with the International Symbol of Accessibility on the interior of the door.	1	\$1,116			
16	Broadacres Farm	H. Emergency Exit	B. Tactile sign not provided at exit D. Illuminated Int. Symbol of Acc. not provided (MAAB)	House - Main Entrance	Exterior	N/A	Priority 2	Navigational Issue	Provide a tactile exit sign with raised characters and braille at the interior of the exit door. Mount sign between 48"- 60" above the finished floor located on the latch side of the door. After the exit is made accessible, provide an illuminated sign with the International Symbol of Accessibility.	1	\$1,116			
17	Broadacres Farm	H. Emergency Exit	B. Tactile sign not provided at exit D. Illuminated Int. Symbol of Acc. not provided (MAAB) C. Directional sign to accessible emergency exit not provided	Horse Riding Practice Building Main Entrance	Exterior	N/A	Priority 2	Navigational Issue	At the interior of the exit door: provide tactile exit signs with raised characters and braille at the existing main exit door and the new accessible main exit door. Provide a directional sign indicating the location of the nearest accessible emergency exit at the inaccessible exit. Provide an illuminated sign with the International Symbol of Accessibility at the accessible exit door.	1	\$1,580			
18	Broadacres Farm	B. Interior Access Route	A. Route < 36" wide	Kitchen Storage and Bathroom	1	N/A	Priority 1	Program Access	Ensure that a clear width of 36" min. is maintained at the accessible route. Remove shelves. Route is allowed to narrow to 32 inches for a depth of 24 inches.	1	\$0			
19	Broadacres Farm	B. Interior Access Route	E. Level changes > 1/4"	Horse Barn Entrance	1	N/A	Priority 1	Program Access	Alter change in level to be 1/4" high max.	1	\$144			
20	Broadacres Farm	B. Interior Access Route	E. Level changes > 1/4"	House - Main Entrance	1	N/A	Priority 1	Program Access	Alter change in level to be 1/4" high max.	1	\$432			
21	Broadacres Farm	B. Interior Access Route	H. Accessible route not provided	Stair	1	N/A	Priority 1	Program Access	Consider locating all public programs on the first floor of the building.	1	\$0			
22	Broadacres Farm	B. Interior Access Route	L. Vertical clearance < 80" above finished floor	Basement	B	N/A	Priority 1	Program Access	The basement is unfinished with tripping hazards, no lighting, and has vertical clearance less than 80" above the floor in some areas. IHCD recommends not providing public programs in this area.	1	\$0			
23	Broadacres Farm	C. Doors, Doorways, & Gates	L. Hardware not operable with a closed fist	Dining Room	1	N/A	Priority 1	Program Access	Provide hardware that can be operable with one hand and not require tight grasping, pinching, or twisting of the wrist.	1	\$484			
24	Broadacres Farm	C. Doors, Doorways, & Gates	L. Hardware not operable with a closed fist	Access to Porch From the Living Room	1	N/A	Priority 1	Program Access	Provide hardware that can be operable with one hand and not require tight grasping, pinching, or twisting of the wrist.	1	\$484			

Information Provided by Institute for Human Centered Design										Status of Barrier Removal				
ID	Facility Name	Element	Issue/Physical Barrier	Location	Floor	Room	Town Priority	Priority for Barrier Removal	Remedies	Quantity	Estimated Cost of Barrier Removal	Barrier Removal Complete (Y/N)	Completion Date (Month/Year)	Completion Date (Fiscal Year)
25	Broadacres Farm	U. Kitchens and Kitchenettes	A. Knee/toe clearance not provided at sink B. Sink > 34" high F. Countertop > 34" high	Kitchen	1	N/A	Priority 1	Program Access	Provide a sink with knee and toe clearance positioned for a forward approach. Lower sink to be no higher than 34" positioned for a forward approach. Lower countertop to provide a work surface no higher than 34" positioned for a forward approach.	1	\$3,974			
26	Broadacres Farm	A. Overall Access	B. Turning space not provided C. Accessible plumbing fixtures or stalls not provided	Horse Barn Toilet Room	1	N/A	Priority 1	Program Access	Add an accessible single-user toilet room.	1	\$24,604			
27	Broadacres Farm	A. Overall Access	B. Turning space not provided C. Accessible plumbing fixtures or stalls not provided	Kitchen Bathroom in the House	1	N/A	Priority 1	Program Access	Provide an accessible single-user toilet room.	1	\$24,604			
28	Broadacres Farm	B. Sink	B. Toe and knee clearances not provided C. Rim or counter > 34" D. Non-compliant faucets	Kitchen Storage Area	1	N/A	Priority 1	Program Access	Ensure there is a 27" knee clearance positioned for a forward approach. Relocate sink with the front of the rim or counter no higher than 34". Install faucets that do not require tight grasping, pinching, or twisting of the wrist.	1	\$4,080			
1	Camp Sewataro - Buildings			Building 1 - Door Between Rear Office and Sun Room	1	N/A	Priority 1	Program Access	Note: From the sun room entrance, if the public is allowed to access the rest of the house, a lift or 17' ramp will need to be installed in this location.	1	\$0			
2	Camp Sewataro - Buildings	C. Off-Street Parking Lot or Garage	A. Total # of parking B. Total # of designated accessible parking spaces C. Total # of designated van accessible spaces	Building 1 - Parking	Exterior	N/A	Priority 1	Program Access	Provide one van accessible parking space.	1	\$1,850			
3	Camp Sewataro - Buildings	G. Entrance	B. Entrance not on an accessible route C. Directional sign to accessible entrance not provided	Building 1 - Route to Entrance	Exterior	N/A	Priority 1	Program Access	Provide a directional sign indicating the location of the nearest accessible entrance.	1	\$346			
4	Camp Sewataro - Buildings	G. Entrance	B. Entrance not on an accessible route	Building 1 - Side Patio	1	N/A	Priority 1	Program Access	Provide a 35' long ramp to this entrance with compliant landings. (Cost estimate for a pressure treated wood dogleg ramp to address a 35" change in level.)	1	\$8,566			
5	Camp Sewataro - Buildings	C. Off-Street Parking Lot or Garage	A. Total # of parking C. Total # of designated van accessible spaces	Building 2	Exterior	N/A	Priority 1	Program Access	Provide one van accessible space.	1	\$1,850			
6	Camp Sewataro - Buildings	B. Interior Access Route	E. Level changes > 1/4"	Building 2 -Main Entrance	1	N/A	Priority 1	Program Access	Provide a compliant wood ramp to address the 12.5" change in level. (Cost estimate for a wood dogleg ramp.)	1	\$5,027			
7	Camp Sewataro - Buildings	G. Entrance	B. Entrance not on an accessible route Q. Hardware not operable with a closed fist	Building 2 -Main Entrance	Exterior	N/A	Priority 1	Program Access	Provide a compliant sloped walkway to the entrance and a level platform at the entrance that provides door maneuvering clearance. Provide hardware that can be operable with one hand and not require tight grasping, pinching, or twisting of the wrist. (Cost estimate for door hardware and a 15' long by 4' wide concrete route.)	1	\$1,864			
8	Camp Sewataro - Buildings	C. Off-Street Parking Lot or Garage	A. Total # of parking C. Total # of designated van accessible spaces	Building 4 - Parking	1	N/A	Priority 1	Program Access	Provide one van accessible space.	1	\$1,850			
9	Camp Sewataro - Buildings	A. Exterior Access Route	N. Accessible route not provided	Building 4 - Main Entrance	1	N/A	Priority 1	Program Access	Ensure an accessible route is provided. Provide a 6' long ramp with compliant platforms at the top and bottom. (Cost estimate for a straight concrete ramp with a 6" rise.)	1	\$7,080			
10	Camp Sewataro - Buildings	G. Entrance	Q. Hardware not operable with a closed fist	Building 4 - Main Entrance	1	N/A	Priority 1	Program Access	Provide hardware that can be operable with one hand and not require tight grasping, pinching, or twisting of the wrist.	1	\$484			
11	Camp Sewataro - Buildings	A. Exterior Access Route	H. Running slope > 1:20 (5%)	Building 4 - Route to Entrance	1	N/A	Priority 1	Program Access	Reduce running slope to be no steeper than 1:20 (5%). Route by entrance has an excessive slope due to tree roots. Address issues when designing ramp at	1	\$0			
12	Camp Sewataro - Buildings	G. Entrance	O. Threshold > 1/2" high Q. Hardware not operable with a closed fist	Building 6 - Barn Entrance	Exterior	N/A	Priority 1	Program Access	Alter threshold to be 1/2" high max. Provide hardware that can be operable with one hand and not require tight grasping, pinching, or twisting of the wrist.	1	\$534			
13	Camp Sewataro - Buildings	C. Off-Street Parking Lot or Garage	C. Total # of designated van accessible spaces A. Total # of parking	Building 6 -Route to Horse Stable Barn	Exterior	N/A	Priority 1	Program Access	Provide one van accessible space.	1	\$1,850			

Information Provided by Institute for Human Centered Design										Status of Barrier Removal				
ID	Facility Name	Element	Issue/Physical Barrier	Location	Floor	Room	Town Priority	Priority for Barrier Removal	Remedies	Quantity	Estimated Cost of Barrier Removal	Barrier Removal Complete (Y/N)	Completion Date (Month/Year)	Completion Date (Fiscal Year)
1	Camp Sewataro - Grounds	A. Exterior Access Route	C. Exterior route < 48" wide K. Surface is not stable, firm, and slip-resistant M. Route not maintained in operable working condition	Garden	Exterior	N/A	Priority 1	Program Access	Ensure that a clear width of 48" min. is maintained at the accessible route. Provide and maintain a stone dust route. (Cost estimate for 180' long, 4' wide stone dust route.)	1	\$5,760			
2	Camp Sewataro - Grounds	A. Exterior Access Route	G. Cross slope > 1:50 (2.00%) H. Running slope > 1:20 (5%)	Sandbox 1	Exterior	N/A	Priority 3	Additional Access	Reduce cross slope to be no steeper than 1:50 (2.00%). Reduce running slope to be no steeper than 1:20 (5%). (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$0			
3	Camp Sewataro - Grounds	A. Exterior Access Route	G. Cross slope > 1:50 (2.00%) H. Running slope > 1:20 (5%)	Picnic Pavilion by Swimming Pond	Exterior	N/A	Priority 3	Additional Access	Reduce cross slope to be no steeper than 1:50 (2.00%). Reduce running slope to be no steeper than 1:20 (5%). (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$0			
4	Camp Sewataro - Grounds	A. Exterior Access Route	G. Cross slope > 1:50 (2.00%) H. Running slope > 1:20 (5%) N. Accessible route not provided	Tennis Courts	Exterior	N/A	Priority 1	Program Access	Ensure an accessible route is provided to the tennis court from a site arrival point and to other areas of sport activity. Reduce cross slope to be no steeper than 1:50 (2.00%). Reduce running slope to be no steeper than 1:20 (5%). (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$0			
5	Camp Sewataro - Grounds	A. Exterior Access Route	G. Cross slope > 1:50 (2.00%) H. Running slope > 1:20 (5%) N. Accessible route not provided	Route to Golf Area	Exterior	N/A	Priority 1	Program Access	Provide an accessible route from a site arrival point and other areas of sport activity. Reduce cross slope to be no steeper than 1:50 (2.00%). Reduce running slope to be no steeper than 1:20 (5%). (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$0			
6	Camp Sewataro - Grounds	A. Exterior Access Route	G. Cross slope > 1:50 (2.00%) N. Accessible route not provided	Route to Men's and Women's Toilet Rooms by Swimming Pool	Exterior	N/A	Priority 1	Program Access	Reduce cross slope to be no steeper than 1:50 (2.00%). Provide an accessible route with a surface that is stable, firm and slip resistant. (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$0	in process	Fall 2023	FY24
7	Camp Sewataro - Grounds	A. Exterior Access Route	H. Running slope > 1:20 (5%)	Sandbox 2	Exterior	N/A	Priority 3	Additional Access	Ensure an accessible route is provided between the site arrival point and sand box area. Reduce running slope to be no steeper than 1:20 (5%). (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$0			
8	Camp Sewataro - Grounds	A. Exterior Access Route	H. Running slope > 1:20 (5%)	Route to Swimming Pool and Toilet Rooms From Liberty Lane	Exterior	N/A	Priority 3	Additional Access	Reduce running slope to be no steeper than 1:20 (5%). (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$0			
9	Camp Sewataro - Grounds	A. Exterior Access Route	H. Running slope > 1:20 (5%) K. Surface is not stable, firm, and slip-resistant N. Accessible route not provided	Route to Men's and Women's Toilet Rooms by Swimming Pool	Exterior	N/A	Priority 1	Program Access	Reduce running slope to be no steeper than 1:20 (5%). Provide an accessible surface that is stable, firm and slip resistant. (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$0	in process	Fall 2023	FY24

Information Provided by Institute for Human Centered Design										Status of Barrier Removal				
ID	Facility Name	Element	Issue/Physical Barrier	Location	Floor	Room	Town Priority	Priority for Barrier Removal	Remedies	Quantity	Estimated Cost of Barrier Removal	Barrier Removal Complete (Y/N)	Completion Date (Month/Year)	Completion Date (Fiscal Year)
10	Camp Sewataro - Grounds	A. Exterior Access Route	H. Running slope > 1:20 (5%) N. Accessible route not provided	Picnic Pavilion East of Garden	Exterior	N/A	Priority 1	Program Access	Reduce running slope to be no steeper than 1:20 (5%). Ensure an accessible route is provided from a site arrival point to the pavilion. (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$0			
11	Camp Sewataro - Grounds	A. Exterior Access Route	H. Running slope > 1:20 (5%) N. Accessible route not provided	Route to Men's and Women's Toilet Rooms by Swimming Pool	Exterior	N/A	Priority 1	Program Access	Reduce running slope to be no steeper than 1:20 (5%). Provide an accessible route with a surface that is stable, firm and slip resistant. (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$0	in process		
12	Camp Sewataro - Grounds	A. Exterior Access Route	J. Level changes > 1/4"	Street Hockey/ Basketball Court by Swimming Area and Camp Craft	Exterior	N/A	Priority 3	Additional Access	Alter change in level to be 1/4" high max. (Cost estimate to patch a 4' x 4' asphalt area.)	1	\$160			
13	Camp Sewataro - Grounds	A. Exterior Access Route	J. Level changes > 1/4"	Golf Area	Exterior	N/A	Priority 3	Additional Access	Alter change in level to be 1/4" high max. (Cost estimate for 5' by 5' asphalt area.)	1	\$250			
14	Camp Sewataro - Grounds	A. Exterior Access Route	J. Level changes > 1/4"	Golf Area	Exterior	N/A	Priority 3	Additional Access	Alter change in level to be 1/4" high max. at one driving range min. (Cost estimate for 5' by 5' asphalt area.)	1	\$250			
15	Camp Sewataro - Grounds	A. Exterior Access Route	K. Surface is not stable, firm, and slip-resistant	Camp Craft Pavilion	Exterior	N/A	Priority 3	Additional Access	Provide a surface at the pavilion that is stable, firm and slip resistant. Surface is currently sand. (Cost for 20' long 4' wide stone dust route.)	1	\$640			
16	Camp Sewataro - Grounds	A. Exterior Access Route	K. Surface is not stable, firm, and slip-resistant	Route to Swimming Pool and Toilet Rooms From Liberty Lane	Exterior	N/A	Priority 3	Additional Access	Remove pavers and install a stone dust route with a running slope no greater than 1:20 (5%). (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$0	in process		
17	Camp Sewataro - Grounds	A. Exterior Access Route	M. Route not maintained in operable working condition N. Accessible route not provided	Sandbox 1	Exterior	N/A	Priority 1	Program Access	Provide an accessible route between the site arrival point and sand box area. Ensure the accessible route is maintained in operable working condition. (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$0			
18	Camp Sewataro - Grounds	A. Exterior Access Route	N. Accessible route not provided	West Garden Entrance	Exterior	N/A	Priority 1	Program Access	Provide an accessible route between the garden and a site arrival point. Ensure it is stable, firm and slip-resistant. (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$0			
19	Camp Sewataro - Grounds	A. Exterior Access Route	N. Accessible route not provided	Picnic Pavilion by Swimming Pond	Exterior	N/A	Priority 1	Program Access	Provide an accessible route from a site arrival point and to other program areas. (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$0			
20	Camp Sewataro - Grounds	A. Exterior Access Route	N. Accessible route not provided	Camp Craft Pavilion	Exterior	N/A	Priority 1	Program Access	Provide an accessible route from a site arrival point and to other program areas. (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$0	Y	8/30/2023	FY24
21	Camp Sewataro - Grounds	A. Exterior Access Route	N. Accessible route not provided	Street Hockey/ Basketball Court by Swimming Area and Camp Craft	Exterior	N/A	Priority 1	Program Access	Provide an accessible route from a site arrival point and between areas of sport activity. (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$0			
22	Camp Sewataro - Grounds	A. Exterior Access Route	N. Accessible route not provided	Kayaking, Canoeing, and Fishing Pond	Exterior	N/A	Priority 1	Program Access	Provide an accessible route from a site arrival point to the pond. (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$0			
23	Camp Sewataro - Grounds	A. Exterior Access Route	N. Accessible route not provided	Gaga Ball Court	Exterior	N/A	Priority 1	Program Access	Provide an accessible route from a site arrival point and other amenities. (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$0			

Information Provided by Institute for Human Centered Design										Status of Barrier Removal				
ID	Facility Name	Element	Issue/Physical Barrier	Location	Floor	Room	Town Priority	Priority for Barrier Removal	Remedies	Quantity	Estimated Cost of Barrier Removal	Barrier Removal Complete (Y/N)	Completion Date (Month/Year)	Completion Date (Fiscal Year)
24	Camp Sewataro - Grounds	A. Exterior Access Route	N. Accessible route not provided	Men's and Women's Toilet Rooms by Swimming Pool Hand Sanitizer Area	Exterior	N/A	Priority 1	Program Access	Locate hand sanitizers on an accessible route.	1	\$0			
25	Camp Sewataro - Grounds	E. Off-Street Parking Lot or Garage	A. Total # of parking B. Total # of designated accessible parking spaces C. Total # of designated van accessible spaces R. Surface not stable, firm, and slip-resistant	Visitor Parking North of Camp Entrance From Haynes Road	Exterior	N/A	Priority 1	Program Access	Provide four (4) car accessible spaces. Provide one (1) van accessible spaces. Provide a surface that is stable, firm and slip resistant such as stone dust at the accessible parking spaces.	5	\$8,260			
26	Camp Sewataro - Grounds	G. Entrance	B. Entrance not on an accessible route	Men's and Women's Toilet Rooms by Swimming Pool	Exterior	N/A	Priority 1	Program Access	Provide a ramp to the entrance. (Cost estimate for a 15' long straight concrete ramp with compliant platforms at the top and bottom.)	1	\$17,702			
27	Camp Sewataro - Grounds	H. Emergency Exit	A. Tactile sign not provided at emergency exit C. Illuminated International Symbol of Acc. not provided (MAAB)	Toilet Rooms by Swimming Pool	1	N/A	Priority 2	Navigational Issue	Provide a sign with raised characters and braille at the emergency exit. After the exit is made accessible provide an illuminated sign with the International Symbol of Accessibility (ISA).	1	\$1,116			
28	Camp Sewataro - Grounds	B. Doors, Doorways, & Gates	N. Hardware not operable with a closed fist	Men's and Women's Toilet Rooms by Swimming Pool	Exterior	N/A	Priority 3	Additional Access	Provide hardware that can be operable with one hand and not require tight grasping, pinching, or twisting of the wrist.	1	\$484			
29	Camp Sewataro - Grounds	E. Signage	Accessible route not provided M. Text size non-compliant	Gaga Ball Court	Exterior	N/A	Priority 1	Program Access	Provided an accessible route to the informational signage. Ensure that character size complies with the Character Height Table 703.5.5 in the ADA 2010 Standards. (Cost does not include accessible route.)	1	\$346			
30	Camp Sewataro - Grounds	E. Signage	B. Raised characters not provided C. Raised characters < 48" or > 60" above ground D. Braille not provided	Men's and Women's Toilet Rooms by Swimming Pool	Exterior	N/A	Priority 2	Navigational Issue	Provide text with raised characters duplicated in braille. Mount signs so that the baseline of the lowest tactile character is 48" min. above the finished floor and the baseline of the highest tactile character is 60" max. above the finished floor.	1	\$346			
31	Camp Sewataro - Grounds	L. Benches	A. No accessible route to one bench in this area	Center of Garden	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to at least one (1) bench in this area. (Cost estimate for 6' long, 4' wide stone dust route from the walkway.)	1	\$192			
32	Camp Sewataro - Grounds	L. Benches	A. No accessible route to one bench in this area	Street Hockey/ Basketball Court by Swimming Area and Camp Craft	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to at least one (1) bench in this area. (Cost estimate for 10' long, 4' wide stone dust walkway from the court.)	1	\$320			
33	Camp Sewataro - Grounds	L. Benches	A. No accessible route to one bench in this area	Golf Area	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to at least one (1) bench in this area. (Cost estimate for 10' long, 4' wide stone dust walkway from the golf area.)	1	\$320			
34	Camp Sewataro - Grounds	L. Benches	A. No accessible route to one bench in this area	Golf Area	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to at least one (1) bench in this area. (Cost estimate for 10' long, 4' wide stone dust walkway from the golf area.)	1	\$320			
35	Camp Sewataro - Grounds	A. Overall Access	B. Turning space not provided C. Accessible plumbing fixtures or stalls not provided	Men's and Women's Toilet Rooms by Swimming Pool	1	N/A	Priority 1	Program Access	Provide one accessible wheelchair compartment for women and one for men.	2	\$12,364			
36	Camp Sewataro - Grounds	A. Drinking Fountains	A. Fountain not on accessible route C. Operable parts malfunctioning E. Spout < 38" or > 43" (standing users) J. No drinking fountain provided for seated users	Near Lacrosse Field	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to drinking fountains. Repair drinking fountains. Provide a drinking fountain for standing users with the spout between 38"- 43" above the finished floor or ground. Provide a drinking fountain for seated users with a 27" high knee clearance or install a Hi-Lo drinking fountain. (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$4,216			

Information Provided by Institute for Human Centered Design										Status of Barrier Removal				
ID	Facility Name	Element	Issue/Physical Barrier	Location	Floor	Room	Town Priority	Priority for Barrier Removal	Remedies	Quantity	Estimated Cost of Barrier Removal	Barrier Removal Complete (Y/N)	Completion Date (Month/Year)	Completion Date (Fiscal Year)
37	Camp Sewataro - Grounds	A. Drinking Fountains	A. Fountain not on accessible route C. Operable parts malfunctioning E. Spout < 38" or > 43" (standing users) J. No drinking fountain provided for seated users	Near Garden Entrance	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to drinking fountains. Repair drinking fountains. Provide a drinking fountain for standing users with the spout between 38"- 43" above the finished floor or ground. Provide a drinking fountain for seated users with a 27" high knee clearance or install a Hi-Lo drinking fountain. (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$4,216			
38	Camp Sewataro - Grounds	A. Drinking Fountains	A. Fountain not on accessible route C. Operable parts malfunctioning E. Spout < 38" or > 43" (standing users) J. No drinking fountain provided for seated users	Drinking Fountains by Tennis Courts	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to drinking fountains. Repair drinking fountains. Provide a drinking fountain for standing users with the spout between 38"- 43" above the finished floor or ground. Provide a drinking fountain for seated users with a 27" high knee clearance or install a Hi-Lo drinking fountain. (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$4,216			
39	Camp Sewataro - Grounds	A. Drinking Fountains	A. Fountain not on accessible route C. Operable parts malfunctioning E. Spout < 38" or > 43" (standing users) J. No drinking fountain provided for seated users	Near Swimming Pond	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to drinking fountains. Repair drinking fountains. Provide a drinking fountain for standing users with the spout between 38"- 43" above the finished floor or ground. Provide a drinking fountain for seated users with a 27" high knee clearance or install a Hi-Lo drinking fountain. (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$4,216			
40	Camp Sewataro - Grounds	C. Field	A. Accessible spaces are not provided at team seating	Softball Field	Exterior	N/A	Priority 1	Program Access	Provide a 36" x 48" clear floor space at team seating. (Cost estimate for 3' x 4' stone dust area.)	1	\$96			
41	Camp Sewataro - Grounds	C. Field	C. Not connected to an accessible-route	Soccer Fields	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to the soccer field from a site arrival point. (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$0			
42	Camp Sewataro - Grounds	C. Field	C. Not connected to an accessible-route	Softball Field	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to the softball field from a site arrival point and other areas of sport activity. (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$0			
43	Camp Sewataro - Grounds	C. Field	C. Not connected to an accessible-route	Fox Field Sports	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to the sports field a site arrival point and other areas of sport activity. (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$0			
44	Camp Sewataro - Grounds	C. Field	C. Not connected to an accessible-route H. Running slope > 1:20 (5%)	Lacrosse Field	Exterior	N/A	Priority 1	Program Access	Reduce running slope to be no steeper than 1:20 (5%). Provide an accessible route to the field from a site arrival point. (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$0			
45	Camp Sewataro - Grounds	D. Court	C. Not connected to accessible route	Volleyball Court	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to the volleyball field from a site arrival point and other areas of sport activity. (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$0			
46	Camp Sewataro - Grounds	D. Court	C. Not connected to accessible route	Gaga Ball Court	Exterior	N/A	Priority 1	Program Access	Provide an accessible entrance into the gaga ball court that is 32" wide min. clear and has a change in level no greater than 1/2".	1	\$0			

Information Provided by Institute for Human Centered Design											Status of Barrier Removal			
ID	Facility Name	Element	Issue/Physical Barrier	Location	Floor	Room	Town Priority	Priority for Barrier Removal	Remedies	Quantity	Estimated Cost of Barrier Removal	Barrier Removal Complete (Y/N)	Completion Date (Month/Year)	Completion Date (Fiscal Year)
47	Camp Sewataro - Grounds	D. Court	C. Not connected to accessible route K. Surface is not stable, firm, and slip-resistant	Street Hockey/ Basketball Court by Tennis Court	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to the street hockey/basketball court from a site arrival point and other areas of sport activity. (Cost does not include an accessible route. Accessible routes will require further study.)	1	\$0			
48	Camp Sewataro - Grounds	N/A	N/A	Liberty Lane To Main Area of Camp	Exterior	N/A	Priority 4	Enhanced Usability	Recommend providing signage that is visible to visitors while driving through the entrance. Existing signage is difficult to read.	1	\$0			
49	Camp Sewataro - Grounds	N/A	N/A	Golf Area and Other Locations	Exterior	N/A	Priority 4	Enhanced Usability	Recommend providing some benches with backs and some with arms. Recommend providing clear floor space alongside benches so that a person using a wheelchair can sit shoulder to shoulder with a person seated on the bench.	1	\$0			
50	Camp Sewataro - Grounds	N/A	N/A	West and East Garden Entrances	Exterior	N/A	Priority 4	Enhanced Usability	Recommend providing a 10" high solid surface (kickplate) on the push side of each gate.	1	\$0			
1	Davis Field	A. Exterior Access Route	H. Running slope > 1:20 (5%) N. Accessible route not provided	Entrance Near Picnic Table on West Side	Exterior	N/A	Priority 1	Program Access	Reduce running slope to be no steeper than 1:20 (5%). Ensure an accessible route is provided. (Cost estimate for a 6' long, 4' wide stone dust route.)	1	\$192			
2	Davis Field	A. Exterior Access Route	H. Running slope > 1:20 (5%) N. Accessible route not provided	Center Entrance to Wayside	Exterior	N/A	Priority 1	Program Access	Reduce running slope to be no steeper than 1:20 (5%). Ensure an accessible route is provided. (Cost estimate for a 4' wide 14' long stone dust route.)	1	\$448			
3	Davis Field	A. Exterior Access Route	N. Accessible route not provided	Wayside and Trash Container	Exterior	N/A	Priority 1	Program Access	Ensure an accessible route is provided. (Cost estimate for a 4' wide 13' long stone dust route.)	1	\$416			
4	Davis Field	E. Off-Street Parking Lot or Garage	A. Total # of parking B. Total # of designated accessible parking spaces	Parking Lot	Exterior	N/A	Priority 1	Program Access	Parking lot has 175-200 spaces estimated. Provide three additional accessible spaces.	3	\$800			
5	Davis Field	E. Off-Street Parking Lot or Garage	G. Access aisle not provided	Parking Lot Near Picnic Table on West Side	Exterior	N/A	Priority 1	Program Access	Provide a marked access aisle that is at least 60" wide.	1	\$300			
6	Davis Field	E. Off-Street Parking Lot or Garage	G. Access aisle not provided	Parking Lot Near Gate Opening on East Side	Exterior	N/A	Priority 1	Program Access	Provide a marked access aisle that is at least 60" wide and a marked vehicle space that is 96" wide min.	1	\$300			
7	Davis Field	E. Off-Street Parking Lot or Garage	G. Access aisle not provided O. Sign does not have the designation "Van Accessible"	Parking Lot Near Wayside Opening in Center	Exterior	N/A	Priority 1	Program Access	Provide a marked access aisle that is at least 96" wide. Add the designation "Van Accessible" to the sign located at the van accessible space.	1	\$800			
8	Davis Field	G. Operable Parts	A. Element not on an accessible route D. Side reach > 54"	Lost and Found on Back of Wayside	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to the lost and found area. Relocate lost and found between 15" - 48" above the finished floor. (Cost estimate for a 20' long 4' wide stone dust route.)	1	\$640			
9	Davis Field	J. Picnic Tables	G. Toe or knee clearance at table not provided H. Picnic table not on an accessible route	Picnic Table Near Parking Lot	Exterior	N/A	Priority 1	Program Access	Provide at least one picnic table with top between 28"- 34" above the ground and 27" clear height underneath. Ensure that the dining surface is connected to an accessible route. (Cost estimate for an accessible picnic table and a 37" long by 4' wide stone dust path from the entrance to the table.)	1	\$2,584			
10	Davis Field	L. Benches	A. No accessible route to one bench in this area	Bench Near Parking Lot	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to at least one bench in this area. (Cost estimate for a 30' long, 4' wide stone dust route.)	1	\$960			
11	Davis Field	C. Field	C. Not connected to an accessible-route	Soccer Nets by Parking Lot and Benches	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to the field. (Cost estimate for 10' long, 4' wide stone dust route.)	1	\$320			
12	Davis Field	N/A	N/A	Picnic Table Near Parking Lot	Exterior	N/A	Priority 4	Enhanced Usability	Recommend providing a 48" wide min. stable, firm and slip resistant surface under and around an accessible picnic table once it is placed in the picnic area and connected to an accessible route.	1	\$0			

Information Provided by Institute for Human Centered Design											Status of Barrier Removal			
ID	Facility Name	Element	Issue/Physical Barrier	Location	Floor	Room	Town Priority	Priority for Barrier Removal	Remedies	Quantity	Estimated Cost of Barrier Removal	Barrier Removal Complete (Y/N)	Completion Date (Month/Year)	Completion Date (Fiscal Year)
13	Davis Field	N/A	N/A	Bench Near Parking Lot	Exterior	N/A	Priority 4	Enhanced Usability	Recommend providing clear floor space of 36" wide minimum by 48" deep alongside one bench so that a wheelchair user can sit alongside someone sitting on the bench.	1	\$0			
1	Featherland Park	A. Exterior Access Route	C. Exterior route < 48" wide	Path Between Baseball Field 1 and Softball Field 2 (Gate)	Exterior	N/A	Priority 1	Program Access	Ensure that gate is opened during operating hours.	1	\$0			
2	Featherland Park	A. Exterior Access Route	J. Level changes > 1/4"	Asphalt Path to Entrance to Baseball Field 3	Exterior	N/A	Priority 3	Additional Access	Alter change in level to be 1/4" high max.	1	\$320			
3	Featherland Park	A. Exterior Access Route	J. Level changes > 1/4" M. Route not maintained in operable working condition	Ice Rink Entrance	Exterior	N/A	Priority 1	Program Access	Alter change in level to be 1/4" high max. Ensure the accessible route is maintained in operable working condition.	1	\$160			
4	Featherland Park	A. Exterior Access Route	M. Route not maintained in operable working condition	Ice Rink Entrance	Exterior	N/A	Priority 1	Program Access	Ensure the accessible route is maintained in operable working condition.	1	\$160			
5	Featherland Park	A. Exterior Access Route	N. Accessible route not provided	South Side of South Concession Between Field 1 and Field 2	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to the toilet room, concession stand and office on the south side of the concession stand. (Cost estimate for 54' long, 4' wide asphalt route.)	1	\$2,160			
6	Featherland Park	A. Exterior Access Route	N. Accessible route not provided	Wayside Signage and Dog Waste Bin Next to Baseball Field 1	Exterior	N/A	Priority 1	Program Access	Ensure an accessible route is provided. (Cost estimate for a 15' long by 4' wide asphalt route.)	1	\$600			
7	Featherland Park	E. Off-Street Parking Lot or Garage	A. Total # of parking B. Total # of designated accessible parking spaces	Parking Lot by Tennis Courts and Ice Rink	Exterior	N/A	Priority 1	Program Access	Provide three car accessible parking spaces and one van accessible parking space in this lot. As best practice, locate at least one of each accessible space by the ice rink, one by the north tennis court and one by the south tennis court.	4	\$3,200			
8	Featherland Park	E. Off-Street Parking Lot or Garage	A. Total # of parking B. Total # of designated accessible parking spaces O. Sign does not have the designation "Van Accessible"	North (Lower Featherland) Parking Lot	Exterior	N/A	Priority 1	Program Access	Add the designation "Van Accessible" to one of the parking spaces.	1	\$500			
9	Featherland Park	G. Entrance	B. Entrance not on an accessible route	South Tennis Court, North Door by Parking Lot, and North and South Doors by Concord Road	Exterior	N/A	Priority 1	Program Access	Provide a directional sign indicating the location of the nearest accessible entrance.	3	\$1,038			
10	Featherland Park	G. Entrance	B. Entrance not on an accessible route	North Tennis/ Basketball Court, Door on South by Concord Road	Exterior	N/A	Priority 1	Program Access	Provide a directional sign indicating the location of the nearest accessible entrance.	1	\$346			
11	Featherland Park	G. Entrance	B. Entrance not on an accessible route	North Tennis/ Basketball Court, Path to the North Entrance by the Parking Lot	Exterior	N/A	Priority 1	Program Access	Provide a directional sign indicating the location of the nearest accessible entrance.	1	\$346			
12	Featherland Park	G. Entrance	B. Entrance not on an accessible route	North Tennis/ Basketball Court, Path to the South Entrance by the Parking Lot	Exterior	N/A	Priority 1	Program Access	Provide a directional sign indicating the location of the nearest accessible entrance.	1	\$346			
13	Featherland Park	G. Entrance	D. International Symbol of Acc. not provided	South Tennis Court, South Door by Parking Lot (Accessible)	Exterior	N/A	Priority 1	Program Access	Provide a sign with the International Symbol of Accessibility (ISA).	1	\$346			
14	Featherland Park	G. Entrance	D. International Symbol of Acc. not provided	North Tennis/ Basketball Court, Door on North by Concord Road	Exterior	N/A	Priority 1	Program Access	Provide a sign with the International Symbol of Accessibility (ISA).	1	\$346			
15	Featherland Park	G. Entrance	O. Threshold is > 1/2" high	Men's Toilet Room in South Concession Between Field 1 and Field 2	Exterior	N/A	Priority 3	Additional Access	Provide an asphalt walkway to the step that is sloped no greater than 1:20 (5%). Cost estimate for 10' long by 4' wide asphalt walkway.	1	\$400			
16	Featherland Park	G. Entrance	Q. Hardware not operable with a closed fist	Women's Toilet Room in South Concession Between Field 1 and Field 2	Exterior	N/A	Priority 3	Additional Access	Provide hardware that can be operable with one hand and not require tight grasping, pinching, or twisting of the wrist.	1	\$484			
17	Featherland Park	A. Interior Access Route	A. Route < 36" wide	South Concession Stand Women's Toilet Room	1	N/A	Priority 3	Additional Access	Ensure that a clear width of 36" min. is maintained at the lavatory when the toilet room is under renovation to add an accessible compartment. 36" clear is required when the depth is greater than 24".	1	\$0			
18	Featherland Park	A. Interior Access Route	A. Route < 36" wide	South Concession Stand Men's Toilet Room	1	N/A	Priority 3	Additional Access	Ensure that a clear width of 36" min. is maintained at the lavatory when the toilet room is under renovation to add an accessible compartment. 36" clear is required when the depth is greater than 24".	1	\$0			
19	Featherland Park	B. Doors, Doorways, & Gates	C. Maneuvering clearance(s) not provided	South Concession Stand Women's Toilet Room Exit to the Exterior	1	N/A	Priority 3	Additional Access	Provide an automatic door opener.	1	\$3,060			

Information Provided by Institute for Human Centered Design												Status of Barrier Removal		
ID	Facility Name	Element	Issue/Physical Barrier	Location	Floor	Room	Town Priority	Priority for Barrier Removal	Remedies	Quantity	Estimated Cost of Barrier Removal	Barrier Removal Complete (Y/N)	Completion Date (Month/Year)	Completion Date (Fiscal Year)
20	Featherland Park	B. Doors, Doorways, & Gates	C. Maneuvering clearance(s) not provided	South Concession Stand Men's Toilet Room Exit to the Exterior	1	N/A	Priority 3	Additional Access	Provide an automatic door opener.	1	\$3,060			
21	Featherland Park	B. Doors, Doorways, & Gates	L. Threshold > 1/2" high	North (Lower Featherland) Concession Stand AED	Exterior	N/A	Priority 3	Additional Access	Alter the threshold to be 1/2" high max.	1	\$150			
22	Featherland Park	B. Doors, Doorways, & Gates	L. Threshold > 1/2" high	North (Lower Featherland) Concession Stand Women's Toilet Room	Exterior	N/A	Priority 3	Additional Access	Alter the threshold to be 1/2" high max.	1	\$150			
23	Featherland Park	B. Doors, Doorways, & Gates	L. Threshold > 1/2" high	North (Lower Featherland) Concession Stand Men's Toilet Room	Exterior	N/A	Priority 3	Additional Access	Alter the threshold to be 1/2" high max.	1	\$150			
24	Featherland Park	B. Doors, Doorways, & Gates	N. Hardware not operable with a closed fist	North (Lower Featherland) Concession Stand AED	Exterior	N/A	Priority 1	Program Access	Provide hardware that can be operable with one hand and not require tight grasping, pinching, or twisting of the wrist.	1	\$484			
25	Featherland Park	B. Doors, Doorways, & Gates	N. Hardware not operable with a closed fist	Men's Toilet Room in South Concession Between Field 1 and Field 2	Exterior	N/A	Priority 1	Program Access	Provide hardware that can be operable with one hand and not require tight grasping, pinching, or twisting of the wrist.	1	\$484			
26	Featherland Park	E. Signage	B. Raised characters not provided D. Braille not provided G. Sign not located on the latch side of the door	Men's Toilet Room in South Concession Between Field 1 and Field 2	Exterior	N/A	Priority 2	Navigational Issue	Provide text with raised characters duplicated in braille. Locate sign at permanent rooms alongside the door on the latch side.	1	\$232			
27	Featherland Park	E. Signage	B. Raised characters not provided D. Braille not provided G. Sign not located on the latch side of the door	Women's Toilet Room in South Concession Between Field 1 and Field 2	Exterior	N/A	Priority 2	Navigational Issue	Provide text with raised characters duplicated in braille. Locate sign at permanent rooms alongside the door on the latch side.	1	\$232			
28	Featherland Park	E. Signage	B. Raised characters not provided D. Braille not provided G. Sign not located on the latch side of the door	North (Lower Featherland) Concession Stand Women's Toilet Room	Exterior	N/A	Priority 2	Navigational Issue	Provide text with raised characters duplicated in braille. Locate sign at permanent rooms alongside the door on the latch side.	1	\$232			
29	Featherland Park	E. Signage	B. Raised characters not provided D. Braille not provided G. Sign not located on the latch side of the door	North (Lower Featherland) Concession Stand Men's Toilet Room	Exterior	N/A	Priority 2	Navigational Issue	Provide text with raised characters duplicated in braille. Locate sign at permanent rooms alongside the door on the latch side.	1	\$232			
30	Featherland Park	F. Service Counter	B. Counter > 36" high	South Concession Stand	1	N/A	Priority 3	Additional Access	Provide a counter that is 36" max. above the ground.	1	\$880			
31	Featherland Park	F. Service Counter	B. Counter > 36" high	South Concession Between Field 1 and Field 2	Exterior	N/A	Priority 3	Additional Access	Provide a counter that is 36" max. above the ground.	1	\$880			
32	Featherland Park	J. Picnic Tables	G. Toe or knee clearance at table not provided	Picnic Area in Front of North Concession Stand in Lower Featherland Park	Exterior	N/A	Priority 1	Program Access	Provide at least one picnic table with top between 28"- 34" above the ground and 27" clear height underneath.	1	\$1,400			
33	Featherland Park	Q. Trash / Recycling	D. Trash container not connected to an accessible route	South Tennis Court, North Door by Parking Lot	Exterior	N/A	Priority 1	Program Access	Ensure trash container is located on an accessible route.	1	\$0			
34	Featherland Park	Q. Trash / Recycling	D. Trash container not connected to an accessible route	Edge of Softball Field 2	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to trash container. (Cost estimate for a 6' long, 4' wide stone dust route.)	1	\$192			
35	Featherland Park	A. Overall Access	C. Accessible plumbing fixtures or stalls not provided	South Concession Stand Women's Toilet Room	1	N/A	Priority 1	Program Access	Provide one accessible wheelchair compartment.	1	\$6,182			
36	Featherland Park	A. Overall Access	C. Accessible plumbing fixtures or stalls not provided	South Concession Stand Men's Toilet Room	1	N/A	Priority 1	Program Access	Provide one accessible wheelchair compartment.	1	\$6,182			
37	Featherland Park	B. Lavatory	B. Toe or knee clearances not provided D. Faucet not operable with a closed fist	South Concession Stand Women's Toilet Room	1	N/A	Priority 1	Program Access	Provide knee and toe clearance positioned for a forward approach. Provide a faucet that can be operable with one hand and not require tight grasping, pinching, or twisting of the wrist at lavatory.	1	\$2,672			
37	Featherland Park	B. Lavatory	E. Exposed plumbing underneath	South Concession Stand Women's Toilet Room	1	N/A	Priority 1	Safety	Insulate or otherwise configure pipes to prevent contact at lavatory.	1	\$92			
38	Featherland Park	B. Lavatory	B. Toe or knee clearances not provided D. Faucet not operable with a closed fist	South Concession Stand Men's Toilet Room	1	N/A	Priority 1	Program Access	Provide knee and toe clearance positioned for a forward approach. Provide a faucet that can be operable with one hand and not require tight grasping, pinching, or twisting of the wrist at lavatory.	1	\$2,672			
38	Featherland Park	B. Lavatory	E. Exposed plumbing underneath	South Concession Stand Men's Toilet Room	1	N/A	Priority 1	Safety	Insulate or otherwise configure pipes to prevent contact at lavatory.	1	\$92			
39	Featherland Park	E. Urinal	A. Rim > 17" high	South Concession Stand Men's Toilet Room	1	N/A	Priority 1	Program Access	Provide at least one urinal with the rim no higher than 17" above the finished floor.	1	\$3,248			
40	Featherland Park	F. Dispensers	A. Controls > 42" (MAAB) E. Dispenser acts as a protruding object	South Concession Stand Women's Toilet Room	1	N/A	Priority 3	Additional Access	Relocate the paper towel dispenser so that the operable part is 42" max. above the finished floor and out of the circulation path.	1	\$256			

Information Provided by Institute for Human Centered Design										Status of Barrier Removal				
ID	Facility Name	Element	Issue/Physical Barrier	Location	Floor	Room	Town Priority	Priority for Barrier Removal	Remedies	Quantity	Estimated Cost of Barrier Removal	Barrier Removal Complete (Y/N)	Completion Date (Month/Year)	Completion Date (Fiscal Year)
41	Featherland Park	C. Field	A. Accessible spaces are not provided at team seating	Baseball Field 1 Entrance Team Seating Area 1	Exterior	N/A	Priority 1	Program Access	Relocate bench to provide a 36" x 48" clear floor space at team seating. Provide a stone dust surface at accessible team seating space.	1	\$96			
42	Featherland Park	C. Field	A. Accessible spaces are not provided at team seating	Baseball Field 1 Entrance Team Seating Area 2	Exterior	N/A	Priority 1	Program Access	Relocate bench to provide a 36" x 48" clear floor space at team seating. Provide a stone dust surface at accessible team seating space.	1	\$96			
43	Featherland Park	C. Field	A. Accessible spaces are not provided at team seating	Baseball Field 5 Team Seating 1	Exterior	N/A	Priority 1	Program Access	Relocate bench to provide a 36" x 48" clear floor space at team seating. Provide a stone dust surface at accessible team seating space.	1	\$96			
44	Featherland Park	C. Field	A. Accessible spaces are not provided at team seating	Baseball Field 5 Team Seating 2	Exterior	N/A	Priority 1	Program Access	Provide a 36" x 48" stone dust surface at accessible team seating space.	1	\$96			
45	Featherland Park	C. Field	A. Accessible spaces are not provided at team seating	Baseball Field 4 Team Seating 1	Exterior	N/A	Priority 1	Program Access	Relocate bench to provide a 36" x 48" clear floor space at team seating. Provide a stone dust surface at accessible team seating space.	1	\$96			
46	Featherland Park	C. Field	A. Accessible spaces are not provided at team seating	Baseball Field 4 Team Seating 2	Exterior	N/A	Priority 1	Program Access	Relocate bench to provide a 36" x 48" clear floor space at team seating. Provide a stone dust surface at accessible team seating space.	1	\$96			
47	Featherland Park	C. Field	A. Accessible spaces are not provided at team seating	Baseball Field 3, Team Seating 1	Exterior	N/A	Priority 1	Program Access	Provide a 36" x 48" stone dust surface at accessible team seating space alongside the bench.	1	\$96			
48	Featherland Park	C. Field	A. Accessible spaces are not provided at team seating	Baseball Field 3, Team Seating 2	Exterior	N/A	Priority 1	Program Access	Relocate bench to provide a 36" x 48" clear floor space at team seating. Provide a stone dust surface at accessible team seating space.	1	\$96			
49	Featherland Park	C. Field	B. Accessible spaces not provided at sidelines seating	Baseball Field 4 Bleacher	Exterior	N/A	Priority 1	Program Access	Provide a 36" x 48" clear floor space on each side of the bleacher. (Cost estimate for 15' long, 4' wide stone dust route.)	2	\$960			
50	Featherland Park	C. Field	B. Accessible spaces not provided at sidelines seating	Baseball Field 3 Bleacher	Exterior	N/A	Priority 1	Program Access	Provide a 36" x 48" clear floor space on each side of the bleacher. (Cost estimate for 15' long, 4' wide stone dust route.)	2	\$960			
51	Featherland Park	C. Field	B. Accessible spaces not provided at sidelines seating C. Not connected to an accessible-route	Baseball Field 1 Bleachers Near Team Seating Area 1	Exterior	N/A	Priority 1	Program Access	Provide a 36" x 48" clear floor space on each side of the bleacher. Provide an accessible route to the bleacher. (Cost estimate for 95' long, 4' wide stone dust route.)	1	\$3,040			
52	Featherland Park	C. Field	B. Accessible spaces not provided at sidelines seating C. Not connected to an accessible-route	Baseball Field 1 Bleachers near Team Seating 2	Exterior	N/A	Priority 1	Program Access	Provide a 36" x 48" clear floor space on each side of the bleacher. Provide an accessible route to the bleacher. (Cost estimate for 103' long, 4' wide stone dust route.)	1	\$3,296			
53	Featherland Park	C. Field	B. Accessible spaces not provided at sidelines seating C. Not connected to an accessible-route	Adult Softball Field 2 Bleachers on South	Exterior	N/A	Priority 1	Program Access	Provide a 36" x 48" clear floor space on each side of each bleacher. Provide an accessible route to the accessible seating area. (Cost estimate for 18' long, 4' wide stone dust route.)	4	\$2,304			
54	Featherland Park	C. Field	B. Accessible spaces not provided at sidelines seating C. Not connected to an accessible-route	Baseball Field 5 Bleacher	Exterior	N/A	Priority 1	Program Access	Relocate bleacher to an accessible route closer to the asphalt. Provide a level 36" x 48" clear floor space on each side of the bleacher. Provide an accessible route to the field. (Cost estimate for 4' long, 4' wide stone dust route.)	2	\$256			
55	Featherland Park	C. Field	C. Not connected to an accessible-route	Baseball Field 1 Entrance	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to the field and to each team seating area. (Cost estimate for 200' long, 4' wide stone dust walkway.)	1	\$6,400			
56	Featherland Park	C. Field	C. Not connected to an accessible-route	Path to Baseball Field 5 Team Seating	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to the baseball field, including to the team seating areas. (Cost estimate for 210' long, 4' wide stone dust route.)	1	\$6,720			

Information Provided by Institute for Human Centered Design											Status of Barrier Removal			
ID	Facility Name	Element	Issue/Physical Barrier	Location	Floor	Room	Town Priority	Priority for Barrier Removal	Remedies	Quantity	Estimated Cost of Barrier Removal	Barrier Removal Complete (Y/N)	Completion Date (Month/Year)	Completion Date (Fiscal Year)
57	Featherland Park	C. Field	C. Not connected to an accessible-route	Entrance to Baseball Field 4	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to the field and team seating areas. (Cost estimate for 120' long, 4' wide stone dust route.)	1	\$3,840			
58	Featherland Park	C. Field	C. Not connected to an accessible-route J. Level changes > 1/4"	Adult Softball Field 2 Team Seating Areas	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to each team seating area. Ensure that level changes are no greater than 1/4" high. (Cost estimate for 12' long, 4' wide asphalt route.)	2	\$960			
59	Featherland Park	C. Field	D. Practice areas are not on an accessible route	Adult Softball Field 2 Pitching Area on South Side	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to the pitching area on the south side. (Cost estimate for 20' long by 4' wide stone dust route.)	1	\$640			
60	Featherland Park	C. Field	D. Practice areas are not on an accessible route	Adult Softball Field 2 Pitching Practice on West Side	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to the pitching area on the west side. (Cost estimate for 10' long, 4' wide stone dust route.)	1	\$320			
61	Featherland Park	C. Field	D. Practice areas are not on an accessible route	Batting Cage	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to practice areas. (Cost estimate for 54' long, 4' wide stone dust route.)	1	\$1,728			
62	Featherland Park	C. Field	F. No accessible route to all areas of sport activity	Entrance to Baseball Field 3	Exterior	N/A	Priority 1	Program Access	Install an accessible route between all areas of sports activity including the team the field, team seating area and batting cage. (Cost estimate for 200' long, 4' wide stone dust route.)	1	\$6,400			
63	Featherland Park	N/A	N/A	Bench Near Baseball Field 5	Exterior	N/A	Priority 4	Enhanced Usability	Recommend providing clear floor space of 36" wide minimum by 48" deep alongside one bench so that a wheelchair user can sit alongside someone sitting on the bench.	1	\$0			
1	Feeley Field	A. Exterior Access Route	M. Route not maintained in operable working condition J. Level changes > 1/4"	Sidewalk Between South Softball and Baseball Fields to North Concession Stand	Exterior	N/A	Priority 1	Program Access	Alter change in level to be 1/4" high max. Ensure the accessible route is maintained in operable working condition.	1	\$160			
2	Feeley Field	A. Exterior Access Route	N. Accessible route not provided	North Concession Stand and Toilet Room Building	Exterior	N/A	Priority 1	Program Access	Ensure an accessible route is provided. (Cost estimate for 50' long concrete ramp to the building.)	1	\$59,007			
3	Feeley Field	A. Exterior Access Route	N. Accessible route not provided	Signage at Tennis Court	Exterior	N/A	Priority 1	Program Access	Relocate wayside sign to an accessible route.	1	\$0			
4	Feeley Field	A. Exterior Access Route	N. Accessible route not provided	Southwest Tennis Entrance From North Softball Field	Exterior	N/A	Priority 1	Program Access	Install an accessible route between all areas of sport activity. (Cost estimate for 6' long by 4' wide stone dust route.)	1	\$192			
5	Feeley Field	E. Off-Street Parking Lot or Garage	A. Total # of parking B. Total # of designated accessible parking spaces C. Total # of designated van accessible spaces	Parking Lot by Tennis Courts	Exterior	N/A	Priority 1	Program Access	Provide one van accessible parking space and one car accessible parking space by the northwest entrance. (Cost of one accessible space, access aisle, sign and striping, including leveling space.)	2	\$3,700			
6	Feeley Field	E. Off-Street Parking Lot or Garage	A. Total # of parking B. Total # of designated accessible parking spaces C. Total # of designated van accessible spaces	Unpaved Lot by North Softball Field	Exterior	N/A	Priority 1	Program Access	Provide four car accessible parking spaces and one van accessible parking space. (Cost estimate for signage and striping.)	5	\$4,000			
7	Feeley Field	E. Off-Street Parking Lot or Garage	A. Total # of parking B. Total # of designated accessible parking spaces G. Access aisle not provided O. Sign does not have the designation "Van Accessible"	Parking Lot by Southwest Softball Field, Accessible Parking Area	Exterior	N/A	Priority 1	Program Access	Provide a marked access aisle for one car accessible and one van accessible parking space. Add the designation "Van Accessible" to the sign located at the van accessible space.	1	\$1,100			
8	Feeley Field	G. Entrance	B. Entrance not on an accessible route	Northwest Tennis Entry	Exterior	N/A	Priority 1	Program Access	Provide an accessible route into the tennis court from the parking lot. (Cost estimate based on a 30' long concrete ramp with handrails).	1	\$35,404			
9	Feeley Field	G. Entrance	C. Directional sign to accessible entrance not provided	North Center Tennis Entrance	Exterior	N/A	Priority 1	Program Access	Provide a directional sign indicating the location of the nearest accessible entrance.	1	\$346			
10	Feeley Field	G. Entrance	C. Directional sign to accessible entrance not provided	Northeast Tennis Entry	Exterior	N/A	Priority 1	Program Access	Provide a directional sign indicating the location of the nearest accessible entrance.	1	\$346			
11	Feeley Field	G. Entrance	D. International Symbol of Acc. not provided	Northwest Tennis Entrance	Exterior	N/A	Priority 1	Program Access	After entrance is made accessible provide signage with the International Symbol of Accessibility (ISA).	1	\$346			

Information Provided by Institute for Human Centered Design											Status of Barrier Removal			
ID	Facility Name	Element	Issue/Physical Barrier	Location	Floor	Room	Town Priority	Priority for Barrier Removal	Remedies	Quantity	Estimated Cost of Barrier Removal	Barrier Removal Complete (Y/N)	Completion Date (Month/Year)	Completion Date (Fiscal Year)
12	Feeley Field	G. Entrance	D. International Symbol of Acc. not provided	Tennis Entrances on South	Exterior	N/A	Priority 1	Program Access	After an accessible route is made to both south entrances, provide a sign with the International Symbol of Accessibility (ISA) at each gate.	2	\$692			
13	Feeley Field	B. Doors, Doorways, & Gates	C. Maneuvering clearance(s) not provided	Women's Toilet Room	1	N/A	Priority 3	Additional Access	Provide an automatic door opener.	1	\$3,060			
14	Feeley Field	B. Doors, Doorways, & Gates	L. Threshold > 1/2" high	Women's and Men's Toilet Room Doors	Exterior	N/A	Priority 3	Additional Access	Threshold is 6" to 10" at the men's and women's toilet room. Recommend providing a raised walkway around building to connect concession counters, and toilet rooms. (Cost estimate based on 107' long, 4' wide min. walkway around building so that the maximum door threshold to both toilet rooms is 1/2 inch.	1	\$6,848			
15	Feeley Field	E. Signage	B. Raised characters not provided D. Braille not provided G. Sign not located on the latch side of the door	Men's Toilet Room	Exterior	N/A	Priority 2	Navigational Issue	Provide text with raised characters duplicated in braille. Locate sign at permanent rooms alongside the door on the latch side.	1	\$232			
16	Feeley Field	E. Signage	B. Raised characters not provided D. Braille not provided G. Sign not located on the latch side of the door	Women's Toilet Room	Exterior	N/A	Priority 2	Navigational Issue	Provide text with raised characters duplicated in braille. Locate sign at permanent rooms alongside the door on the latch side.	1	\$232			
17	Feeley Field	F. Service Counter	A. Not connected to a accessible route B. Counter > 36" high	North Concession Stand	Exterior	N/A	Priority 1	Program Access	Ensure the counter is connected to an accessible route. Provide a counter that is 36" max. above the ground. (Note: If a raised walkway or plinth is built around the building, concession counter may not need to be lowered.)	1	\$880			
18	Feeley Field	F. Service Counter	A. Not connected to a accessible route B. Counter > 36" high	North Concession Stand	Exterior	N/A	Priority 1	Program Access	Ensure the counter is connected to an accessible route. Provide a counter that is 36" max. above the ground. (Note: If a raised walkway or plinth is built around the building, concession counter may not need to be lowered.)	1	\$880			
19	Feeley Field	F. Service Counter	B. Counter > 36" high	Baseball Field Concession Stand	Exterior	N/A	Priority 3	Additional Access	Provide a counter that is 36" max. above the ground.	1	\$880			
20	Feeley Field	J. Picnic Tables	G. Toe or knee clearance at table not provided	North Concession Stand Picnic Area	Exterior	N/A	Priority 1	Program Access	Provide at least one picnic table with top between 28"- 34" above the ground and 27" clear height underneath. Ensure it is located on an accessible route.	1	\$1,400			
21	Feeley Field	L. Benches	A. No accessible route to one bench in this area	Seating at North Softball Field	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to at least one bench in this area. (Cost estimate for 4' long by 4' wide stone dust route.)	1	\$128			
22	Feeley Field	Q. Trash / Recycling	D. Trash container not connected to an accessible route	North Center Tennis Entrance	Exterior	N/A	Priority 1	Program Access	Ensure trash container is located on an accessible route.	1	\$0			
23	Feeley Field	A. Overall Access	C. Accessible plumbing fixtures or stalls not provided B. Toe or knee clearances not provided D. Faucet not operable with a closed fist E. Exposed plumbing underneath lavatory A. Urinal rim > 17" high B. Clear floor space not provided at urinal C. Flush control too high or not properly located at urinal	Men's Toilet Room	1	N/A	Priority 1	Program Access	Renovate toilet room to be an accessible single-user toilet room. Provide a faucet that can be operable with one hand and not require tight grasping, pinching, or twisting of the wrist for at least one lavatory. Insulate or otherwise configure pipes to prevent contact at lavatory. Provide at least one lavatory with knee and toe clearance positioned for a forward approach.	1	\$24,604			
24	Feeley Field	A. Overall Access	C. Accessible plumbing fixtures or stalls not provided D. Faucet not operable with a closed fist E. Exposed plumbing underneath	Women's Toilet Room	1	N/A	Priority 1	Program Access	Renovate toilet room to be an accessible single-user toilet room. Provide a faucet that can be operable with one hand and not require tight grasping, pinching, or twisting of the wrist for at least one lavatory. Insulate or otherwise configure pipes to prevent contact at lavatory.	1	\$24,604			
25	Feeley Field	C. Field	A. Accessible spaces are not provided at team seating	North Softball Field, Team Seating Area	Exterior	N/A	Priority 1	Program Access	Provide a 36" x 48" clear floor space at team seating alongside bench. (Cost estimate for 3' by 4' stone dust area.)	2	\$192	Y	Jul-24	FY25

Information Provided by Institute for Human Centered Design											Status of Barrier Removal			
ID	Facility Name	Element	Issue/Physical Barrier	Location	Floor	Room	Town Priority	Priority for Barrier Removal	Remedies	Quantity	Estimated Cost of Barrier Removal	Barrier Removal Complete (Y/N)	Completion Date (Month/Year)	Completion Date (Fiscal Year)
26	Feeley Field	C. Field	A. Accessible spaces are not provided at team seating C. Not connected to an accessible-route	Southeast Softball Field Team Seating	Exterior	N/A	Priority 1	Program Access	Provide a 36" x 48" clear floor space at team seating. Provide an accessible route to the field. (Cost estimate for 420' 4' wide stone dust route from southwest softball field.)	1	\$13,440	Y	Summer 2025	FY25
27	Feeley Field	C. Field	A. Accessible spaces are not provided at team seating F. No accessible route to all areas of sport activity	Southwest Softball Field Team Seating	Exterior	N/A	Priority 1	Program Access	Provide a 36" x 48" clear floor space at each team seating area Install an accessible route to each team seating area. (Cost estimate for 216' long, 4' wide stone dust route from the parking lot.)	1	\$6,912	Y	Summer 2025	FY25
28	Feeley Field	C. Field	B. Accessible spaces not provided at sidelines seating	Baseball Field, Access to Bleachers	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to team seating area from the parking lot to the north. Provide a 36" x 48" clear floor space on each side of the bleacher. (Cost estimate for 173' long, 4' wide stone dust route.)	1	\$5,536	Y		
29	Feeley Field	C. Field	B. Accessible spaces not provided at sidelines seating	Baseball Field, Bleacher In Front of Press Box	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to sideline seating and a 36" x 48" clear floor space alongside each side of bleacher. (Cost estimate for 34' long, 4' wide stone dust route.)	1	\$1,088			
30	Feeley Field	C. Field	B. Accessible spaces not provided at sidelines seating D. Practice areas are not on an accessible route	North Softball Field Batting Cage and Spectator Seating	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to sidelines seating and provide a 36" x 48" clear floor space alongside each side of bleacher. Provide an accessible route to the batting cage. (Cost estimate for 102' long, 4' wide stone dust route.)	1	\$3,264	in process	Summer 2026	FY27
31	Feeley Field	C. Field	C. Not connected to an accessible-route	Baseball Field, Entrance to North Team Seating Area	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to the the north team seating area. (Cost estimate for 6' long, 4' wide asphalt route.)	1	\$240			
32	Feeley Field	C. Field	C. Not connected to an accessible-route	Baseball Field, West Team Seating Area	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to the the west team seating area. (Cost estimate for 15' long, 4' wide asphalt route.)	1	\$600			
33	Feeley Field	C. Field	C. Not connected to an accessible-route F. No accessible route to all areas of sport activity	North Softball Field Team Seating Areas	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to the field and to team seating areas. (Cost estimate for 305' long, 4' wide stone dust route.)	1	\$9,760	in process	Summer 2026	FY27
34	Feeley Field	C. Field	D. Practice areas are not on an accessible route	Baseball Field, Batting Cages	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to practice areas. (Cost estimate for 12' long, 4' wide asphalt route.)	1	\$480			
35	Feeley Field	C. Field	D. Practice areas are not on an accessible route	Baseball Field, Route Between North Team Seating Area and Pitching Practice Area	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to pitching practice area. (Cost estimate for 10' long, 4' wide asphalt route.)	1	\$400			
36	Feeley Field	C. Field	D. Practice areas are not on an accessible route	Baseball Field, Route Between West Team Seating Area and Pitching Practice Area	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to practice areas. (Cost estimate for 12' long, 4' wide asphalt route.)	1	\$480			
37	Feeley Field	D. Court	F. No accessible route between all areas of sport activity	Tennis Entry on Southeast From North Softball Field	Exterior	N/A	Priority 1	Program Access	Install an accessible route between the tennis court and softball field. (Cost estimate for 4' long by 4' wide stone dust route.)	1	\$128			
38	Feeley Field	N/A	N/A	Baseball Field, Path to Upper Level Bleachers	Exterior	N/A	Priority 4	Enhanced Usability	Recommend providing handrails at the stepped route to spectator seating.	1	\$0			
39	Feeley Field	N/A	N/A	North Concession Stand and Toilet Rooms	Exterior	N/A	Priority 4	Enhanced Usability	Recommend providing an accessible route from this facility to the sidewalk.	1	\$0			
40	Feeley Field	N/A	N/A	Seating at North Softball Field	Exterior	N/A	Priority 4	Enhanced Usability	Recommend providing clear floor space of 36" wide minimum by 48" deep alongside one bench so that a wheelchair user can sit alongside someone sitting on the bench.	1	\$0	in process	Summer 2026	FY27
1	Grinnell Park	A. Exterior Access Route	G. Cross slope > 1:50 (2.00%)	Walkway Southwest of World War I Memorial	Exterior	N/A	Priority 3	Additional Access	Reduce cross slope to be no steeper than 1:50 (2.00%). (Cost based on 4'x15' of stone dust to correct slope.)	1	\$480			

Information Provided by Institute for Human Centered Design											Status of Barrier Removal			
ID	Facility Name	Element	Issue/Physical Barrier	Location	Floor	Room	Town Priority	Priority for Barrier Removal	Remedies	Quantity	Estimated Cost of Barrier Removal	Barrier Removal Complete (Y/N)	Completion Date (Month/Year)	Completion Date (Fiscal Year)
2	Grinnell Park	A. Exterior Access Route	G. Cross slope > 1:50 (2.00%)	Walkway West of World War I Memorial	Exterior	N/A	Priority 3	Additional Access	Reduce cross slope to be no steeper than 1:50 (2.00%). (Cost based on 4'x6' of stone dust to correct slope.)	1	\$192			
3	Grinnell Park	A. Exterior Access Route	M. Route not maintained in operable working condition	Walkway Southeast of World War I Memorial	Exterior	N/A	Priority 1	Program Access	Ensure the accessible route is maintained in operable working condition.	1	\$0			
4	Grinnell Park	A. Exterior Access Route	P. Detectable warning not provided	Crosswalk at the Intersection of Hudson and Concord Roads	Exterior	N/A	Priority 1	Program Access	Provide a detectable warning on the curb ramp.	1	\$360			
5	Grinnell Park	L. Benches	A. No accessible route to one bench in this area	Southeast End of the Park	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to at least one bench in this area. (Cost based on a new 4' wide min. x 15' stone dust path.)	1	\$600	in planning		
6	Grinnell Park	Bench	N/A	Walkway From World War I Memorial to the Intersection of Hudson and Concord Roads	Exterior	N/A	Priority 4	Enhanced Usability	Recommend providing a bench with a 36" min. x 48" min. wide stable, firm and slip resistant surface such as stone dust at one end by the pathway the runs along Hudson Road to provide a location near the memorial for visitors to rest while at the park.	1	\$0	Y		FY25
7	Grinnell Park	Clear Floor Space by Bench	N/A	Southeast End of the Park	Exterior	N/A	Priority 4	Enhanced Usability	Recommend providing a 36" min. x 48" min. wide stable, firm and slip resistant surface such as stone dust at one end of one of the benches in this area once the bench is connected to an accessible	1	\$0			
1	Haskell Field	A. Exterior Access Route	E. Route obstructed by protruding objects	Library - Children's Playground	Exterior	N/A	Priority 3	Additional Access	Provide a cane-detectable barrier below book exchange 27" max. above the ground. (Book exchange protrudes 15.75".)	1	\$306	in planning		
2	Haskell Field	A. Exterior Access Route	H. Running slope > 1:20 (5%)	Left Side Entrance From Parking 3 to Soccer Fields	Exterior	N/A	Priority 3	Additional Access	Reduce running slope to be no steeper than 1:20 (5%), reduce change in level from parking to soccer field entrance to 1/2" max.	1	\$0	in planning		
3	Haskell Field	A. Exterior Access Route	M. Route not maintained in operable working condition	Path to Children's Playground	Exterior	N/A	Priority 1	Program Access	Ensure the accessible route is maintained in operable working condition.	1	\$0	in process		FY27
4	Haskell Field	A. Exterior Access Route	N. Accessible route not provided	Wayside Next to Parking 3	Exterior	N/A	Priority 1	Program Access	Ensure an accessible route is provided to the wayside and the dog waste bag dispenser. Either relocate both to an accessible location or provide a firm, stable and slip resistant route to both. (Cost based on a 4' wide min. x 15' long stone dust path to both amenities.)	1	\$480	in planning		
5	Haskell Field	A. Exterior Access Route	N. Accessible route not provided	From Right Side of Parking 1 to Accessible Path 2	Exterior	N/A	Priority 1	Program Access	Ensure an accessible route is provided between the parking lot and the existing accessible path. (Cost based on a 4' wide min. x 15' firm, stable and slip resistant accessible path to the existing path.)	1	\$960	in process		FY27
6	Haskell Field	E. Signage	Sign not maintained in operable working condition	Men's Toilet Room	Exterior	N/A	Priority 2	Navigational Issue	Provide new sign with raised characters and braille.	1	\$232	in planning		
7	Haskell Field	F. Service Counter	B. Counter > 36" high	Concession Stand - Children's Playground	Exterior	N/A	Priority 3	Additional Access	Provide a counter that is 36" max. above the ground.	1	\$880	in planning		
8	Haskell Field	G. Operable Parts	C. Reach < 15" or > 48" (forward/side approach)	Wayside	Exterior	N/A	Priority 3	Additional Access	Reposition dog waste bag dispenser to between 15"- 48" above the finished floor.	1	\$0	in planning		
9	Haskell Field	J. Picnic Tables	G. Toe or knee clearance at table not provided	Picnic Table Near Accessible Play Structure 1 - Children's Playground	Exterior	N/A	Priority 1	Program Access	Provide at least one picnic table in this area with top between 28"- 34" above the ground and 27" clear height underneath.	1	\$1,400	in planning		
10	Haskell Field	J. Picnic Tables	G. Toe or knee clearance at table not provided H. Picnic table not on an accessible route	Picnic Tables Next to Parking 3	Exterior	N/A	Priority 1	Program Access	Provide at least one picnic table with top between 28"- 34" above the ground and 27" clear height underneath. Ensure that the dining surface is connected to an accessible route.	1	\$1,400	in planning		

Information Provided by Institute for Human Centered Design										Status of Barrier Removal				
ID	Facility Name	Element	Issue/Physical Barrier	Location	Floor	Room	Town Priority	Priority for Barrier Removal	Remedies	Quantity	Estimated Cost of Barrier Removal	Barrier Removal Complete (Y/N)	Completion Date (Month/Year)	Completion Date (Fiscal Year)
11	Haskell Field	J. Picnic Tables	G. Toe or knee clearance at table not provided H. Picnic table not on an accessible route	Opening 1 Near Accessible Path 2 From Right Side of Parking 1	Exterior	N/A	Priority 1	Program Access	Provide at least one picnic table with top between 28"- 34" above the ground and 27" clear height underneath. Ensure that the dining surface is connected to an accessible route. (Cost based on an accessible picnic table and a 4' wide min. x 15' firm, stable and slip resistant accessible path to the picnic table.)	1	\$2,360	in planning		
12	Haskell Field	J. Picnic Tables	G. Toe or knee clearance at table not provided H. Picnic table not on an accessible route	Picnic Tables Near Parking 3	Exterior	N/A	Priority 1	Program Access	Provide at least one picnic table with top between 28"- 34" above the ground and 27" clear height underneath. Ensure that the accessible picnic table in this area is connected to an accessible route.	1	\$1,400	in planning		
13	Haskell Field	J. Picnic Tables	H. Picnic table not on an accessible route	Outdoor Play Gym	Exterior	N/A	Priority 1	Program Access	Ensure that the picnic table is connected to an accessible route. (Cost based on a stone dust patch, 3'x4' min., at the accessible end of the accessible picnic table.)	1	\$240	in planning		
14	Haskell Field	L. Benches	A. No accessible route to one bench in this area	Bench Next to Children's Playground	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to at least one bench in this area. (Cost based on a 4' wide min. x 15' long stone dust path to bench.)	1	\$480	in planning		
15	Haskell Field	L. Benches	A. No accessible route to one bench in this area	Baseball Seating	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to at least one bench in this area and to the trash receptacle or relocate both to an accessible route. (Cost based on a 4' wide min. x 6' firm, stable and slip resistant path to bench and trash receptacle.)	1	\$240	in planning		
16	Haskell Field	L. Benches	A. No accessible route to one bench in this area	Right Side Soccer Field	Exterior	N/A	Priority 1	Program Access	Install an accessible route with a 5.00% max. running and 2.00% max. cross slope between towards benches and the resumed accessible path. (Cost based on a 4' wide min. x 60' long path leading towards benches and the resumed accessible path.)	1	\$1,920	in planning		
17	Haskell Field	L. Benches	A. No accessible route to one bench in this area	Accessible Path 2	Exterior	N/A	Priority 1	Program Access	Install an accessible route with a 5.00% max. running and 2.00% max. cross slope between towards benches and the resumed accessible path. (Cost based on a 4' wide min. x 60' long path leading towards benches and the resumed accessible path.)	1	\$1,920	in process		
18	Haskell Field	Q. Trash / Recycling	D. Trash container not connected to an accessible route	Left Side Entrance From Parking 3 to Soccer Fields	Exterior	N/A	Priority 1	Program Access	Ensure trash container is located on an accessible route.	1	\$0	in planning		
19	Haskell Field	Q. Trash / Recycling	D. Trash container not connected to an accessible route	Path 2	Exterior	N/A	Priority 1	Program Access	Ensure trash container is located on an accessible route.	1	\$0	in planning		
20	Haskell Field	A. Overall Access	H. Audible and visible alarms not provided	Men's Toilet Room	Exterior	N/A	Priority 3	Additional Access	When fire system is updated, ensure that a visible and audible fire alarm is installed.	1	\$0	in planning		
21	Haskell Field	C. Single-User Toilet		Women's Accessible Toilet Room	Exterior	N/A			This toilet room was locked on the day that IHCD was at Haskell Field and could not be surveyed.	1	\$0	in planning		
22	Haskell Field	A. Drinking Fountains	H. No drinking fountain provided for standing users	Fountain - Children's Playground	Exterior	N/A	Priority 1	Program Access	Provide an additional drinking fountain for standing users or install a Hi-Lo drinking fountain.	1	\$4,028	in planning		
23	Haskell Field	B. Play Areas	B. Accessible route not provided at play components	Accessible Play Structure 2 - Children's Playground	Exterior	N/A	Priority 1	Program Access	Reduce change in level to 1/2" max.	1	\$0	Y		FY26
24	Haskell Field	B. Play Areas	B. Accessible route not provided at play components	Play Structure 3 - Children's Playground	Exterior	N/A	Priority 1	Program Access	Provide a compliant impact-attenuating surface under and around the play components. Note: IHCD team has been told that Sudbury has budgeted \$163,000 to address this issue at Haskell Field.	1	\$0	Y		FY26
25	Haskell Field	B. Play Areas	N. Play areas not maintained in operable working condition	Near Climber	Exterior	N/A	Priority 1	Program Access	Ensure play area is maintained in operable working condition/repair patch as needed.	1	\$0	Y		FY26
26	Haskell Field	B. Play Areas	N. Play areas not maintained in operable working condition	Accessible Play Structure 2 - Children's Playground	Exterior	N/A	Priority 1	Program Access	Ensure play area is maintained in operable working condition.	1	\$0	Y		FY26

Information Provided by Institute for Human Centered Design										Status of Barrier Removal				
ID	Facility Name	Element	Issue/Physical Barrier	Location	Floor	Room	Town Priority	Priority for Barrier Removal	Remedies	Quantity	Estimated Cost of Barrier Removal	Barrier Removal Complete (Y/N)	Completion Date (Month/Year)	Completion Date (Fiscal Year)
27	Haskell Field	B. Play Areas	N. Play areas not maintained in operable working condition	Ground Play Components	Exterior	N/A	Priority 1	Program Access	Ensure play area is maintained in operable working condition.	1	\$0	Y		FY26
28	Haskell Field	C. Field	A. Accessible spaces are not provided at team seating	Path 1 Baseball Seating	Exterior	N/A	Priority 1	Program Access	Provide a 48" wide min. firm, stable and slip resistant path to team seating with a 5.00% max. running and 2.00% max. cross slope. (Cost based on a 48" wide x 15' long stone dust path.)	1	\$480	in planning		
29	Haskell Field	C. Field	A. Accessible spaces are not provided at team seating	Baseball Seating	Exterior	N/A	Priority 1	Program Access	Provide a 36" x 48" clear floor space at team seating.	1	\$0	in planning		
30	Haskell Field	C. Field	A. Accessible spaces are not provided at team seating	Baseball Seating 2	Exterior	N/A	Priority 1	Program Access	Provide a 36" x 48" clear floor space at team seating.	1	\$0	in planning		
31	Haskell Field	C. Field	B. Accessible spaces not provided at sidelines seating	Bleachers	Exterior	N/A	Priority 1	Program Access	Provide a 4' wide min. firm, stable and slip resistant route to the sideline seating bleachers with a 5.00% max. running and 2.00% max. cross slope. Provide a 36" x 48" clear floor space at sidelines seating. (Cost based on a 4' wide min. x 30' path.)	1	\$960	in planning		
32	Haskell Field	C. Field	C. Not connected to an accessible-route	Baseball Dugout to Field	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to the field. Widen gate to 32" min.	1	\$0	in planning		
33	Haskell Field	C. Field	C. Not connected to an accessible-route	Towards Baseball Seating 2	Exterior	N/A	Priority 1	Program Access	Provide a 4' wide min. firm, stable and slip resistant route to the equipment storage shed, the boundary of sport activity, and to the second team seating dugout with a 5.00% max. running and 2.00% max. cross slope at baseball. (Cost based on a 4' wide min. x 60' path.)	1	\$1,920	in planning		
34	Haskell Field	C. Field	C. Not connected to an accessible-route	Baseball Seating 2	Exterior	N/A	Priority 1	Program Access	Reduce change in level to 1/2" max. (Cost based on a concrete patch.)	1	\$256	in planning		
35	Haskell Field	C. Field	C. Not connected to an accessible-route	Batting Cage	Exterior	N/A	Priority 1	Program Access	Provide a firm, stable and slip resistant accessible route to the batting cage entry with a 5.00% max. running and 2.00% max. cross slope.	1	\$960	in planning		
36	Haskell Field	C. Field	F. No accessible route to all areas of sport activity	Right Side of Soccer Field	Exterior	N/A	Priority 1	Program Access	Install an accessible route with a 5.00% max. running and 2.00% max. cross slope between the existing path and boundary of sport activity at the soccer field. (Cost based on a 4' wide min. x 60' long path leading towards the benches and the resumed accessible path.)	1	\$1,920	in process		FY27
37	Haskell Field	Bench	N/A	Bench 1 on Path 1	Exterior	N/A	Priority 4	Enhanced Usability	Recommend providing a 3'x4' asphalt patch at one end of bench.	1	\$0	in process		FY26
38	Haskell Field	Bench	N/A	Bench 2 on Path 1	Exterior	N/A	Priority 4	Enhanced Usability	Recommend providing a 3'x4' asphalt patch at one end of bench.	1	\$0	in process		FY26
39	Haskell Field	Bench	N/A	Path 2	Exterior	N/A	Priority 4	Enhanced Usability	Recommend relocate bench closer to existing accessible route and providing a 3'x4' asphalt patch at one end of bench.	1	\$0	in process		FY26
40	Haskell Field	Bench	N/A	Bench 3 on Path 2	Exterior	N/A	Priority 4	Enhanced Usability	Recommend providing a 3'x4' asphalt patch at one end of bench.	1	\$0	in process		FY26
41	Haskell Field	Men's Toilet Room	N/A	Men's Toilet Room	Exterior	N/A	Priority 4	Enhanced Usability	Recommend providing a sign with the International Symbol of Accessibility (ISA) at the men's toilet room.	1	\$0	in planning		
42	Haskell Field	Picnic Table	N/A	Picnic Tables Near Parking 3	Exterior	N/A	Priority 4	Enhanced Usability	Recommend providing a 48" min. firm, stable and slip resistant surface around the exterior of each accessible picnic table in the park.	1	\$0	in planning		
1	Heritage Park	A. Exterior Access Route	C. Exterior route < 48" wide	Walkway South of Pond	Exterior	N/A	Priority 3	Additional Access	Ensure that a clear width of 48" min. is maintained at the accessible route. (Cost estimate for labor and 20' long 4' wide stone dust route.)	1	\$640	Y	5/1/2023	FY23
2	Heritage Park	A. Exterior Access Route	C. Exterior route < 48" wide G. Cross slope > 1:50 (2.00%) H. Running slope > 1:20 (5%)	Dogwood Path	Exterior	N/A	Priority 3	Additional Access	Ensure that a clear width of 48" min. is maintained at the accessible route. Reduce cross slope to be no steeper than 1:50 (2.00%). Reduce running slope to be no steeper than 1:20 (5%). (Cost estimate for a 530' long, 4' wide stone dust path.)	1	\$16,960			

Information Provided by Institute for Human Centered Design										Status of Barrier Removal				
ID	Facility Name	Element	Issue/Physical Barrier	Location	Floor	Room	Town Priority	Priority for Barrier Removal	Remedies	Quantity	Estimated Cost of Barrier Removal	Barrier Removal Complete (Y/N)	Completion Date (Month/Year)	Completion Date (Fiscal Year)
3	Heritage Park	A. Exterior Access Route	F. Surface openings > 1/2" H. Running slope > 1:20 (5%)	9/11 Memorial	Exterior	N/A	Priority 3	Additional Access	Ensure that surface has openings that are 1/2" max. and the long opening dimension is perpendicular to the dominant direction of travel. Reduce running slope to be no steeper than 1:20 (5%). (Cost estimate for a 14' long 4' wide stone dust route.)	1	\$560			
4	Heritage Park	A. Exterior Access Route	H. Running slope > 1:20 (5%)	Walkway South of Pond	Exterior	N/A	Priority 3	Additional Access	Reduce running slope to be no steeper than 1:20 (5%). (Cost estimate for a 6' long 4' wide stone dust area.)	1	\$240			
5	Heritage Park	A. Exterior Access Route	H. Running slope > 1:20 (5%)	Walkway South of Pond	Exterior	N/A	Priority 3	Additional Access	Reduce running slope to be no steeper than 1:20 (5%). (Cost estimate for a 12' long 4' wide stone dust area.)	1	\$480			
6	Heritage Park	A. Exterior Access Route	J. Level changes > 1/4"	Dogwood Path	Exterior	N/A	Priority 3	Additional Access	Alter change in level to be 1/4" high max. (Cost estimate for providing a 12' by 4' stone dust area.)	1	\$480			
7	Heritage Park	A. Exterior Access Route	J. Level changes > 1/4"	Dogwood Path Bridge	Exterior	N/A	Priority 3	Additional Access	Alter change in level to be 1/4" high max. (Cost estimate for providing a 4' by 4' stone dust area.)	1	\$160			
8	Heritage Park	A. Exterior Access Route	M. Route not maintained in operable working condition O. Vertical clearance < 80" above ground	Walkway from Pond to Concord Road	Exterior	N/A	Priority 1	Program Access	Ensure the accessible route is maintained in operable working condition. Trim low hanging tree branches. (Cost estimate for a 20' long 4' wide stone dust route.)	1	\$840	Y	5/1/2023	FY23
9	Heritage Park	A. Exterior Access Route	N. Accessible route not provided	Cricket Pond	Exterior	N/A	Priority 1	Program Access	Locate sign identifying pond on an accessible route.	1	\$0			
10	Heritage Park	A. Exterior Access Route	N. Accessible route not provided	Dogwood Path Plaque	Exterior	N/A	Priority 1	Program Access	Ensure an accessible route is provided to the plaque. (Cost estimate for a 6' long by 4' wide stone dust walkway.)	1	\$192			
11	Heritage Park	A. Exterior Access Route	N. Accessible route not provided	Entrance from Dogwood Path to 9/11 Memorial	Exterior	N/A	Priority 1	Program Access	Ensure an accessible route is provided between the dogwood path and the 9/11 Memorial path. (Cost estimate for a 20' long by 4' wide stone dust walkway.)	1	\$640			
12	Heritage Park	A. Exterior Access Route	N. Accessible route not provided	Near Stairs to Old Sudbury Road	Exterior	N/A	Priority 1	Program Access	Ensure an accessible route is provided. (Cost estimate for a 6' long by 4' wide stone dust walkway.)	1	\$192			
13	Heritage Park	A. Exterior Access Route	N. Accessible route not provided	Plaque Along Walkway by Pond and 9/11 Memorial	Exterior	N/A	Priority 1	Program Access	Ensure an accessible route is provided. (Cost estimate for a 10' long by 4' wide stone dust walkway.)	1	\$320			
14	Heritage Park	A. Exterior Access Route	N. Accessible route not provided	Walkway from Pond to Concord Road	Exterior	N/A	Priority 1	Program Access	Ensure an accessible route is provided to each plaque. (Cost estimate for a 6' long by 4' wide stone dust walkway.)	2	\$384			
15	Heritage Park	G. Entrance	B. Entrance not on an accessible route	Main Entrance from Old Sudbury Road	Exterior	N/A	Priority 1	Program Access	Provide a directional sign indicating the location of the nearest accessible entrance.	1	\$346			
16	Heritage Park	D. Stairways	N. Handrails not provided	Main Entrance from Old Sudbury Road	Exterior	N/A	Priority 3	Additional Access	Provide handrails. (Cost estimate for 20' of metal handrail.)	1	\$1,480			
17	Heritage Park	J. Picnic Tables	G. Toe or knee clearance at table not provided H. Picnic table not on an accessible route	Near Old Sudbury Road Entrance	Exterior	N/A	Priority 1	Program Access	Provide at least one picnic table with top between 28"- 34" above the ground and 27" clear height underneath. Ensure that the dining surface is connected to an accessible route. (Cost for an accessible picnic table.)	1	\$1,400			
18	Heritage Park	J. Picnic Tables	G. Toe or knee clearance at table not provided H. Picnic table not on an accessible route	Walkway South of Pond	Exterior	N/A	Priority 1	Program Access	Provide at least one picnic table with top between 28"- 34" above the ground and 27" clear height underneath. Ensure that the dining surface is connected to an accessible route. (Cost estimate for 20' long 4' wide stone dust walkway and a new accessible picnic table.)	1	\$2,040			
19	Heritage Park	L. Benches	A. No accessible route to one bench in this area	Along Walkway by Pond	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to at least one bench in this area. (Cost estimate for a 10' long by 4' wide stone dust walkway.)	1	\$320			

Information Provided by Institute for Human Centered Design											Status of Barrier Removal			
ID	Facility Name	Element	Issue/Physical Barrier	Location	Floor	Room	Town Priority	Priority for Barrier Removal	Remedies	Quantity	Estimated Cost of Barrier Removal	Barrier Removal Complete (Y/N)	Completion Date (Month/Year)	Completion Date (Fiscal Year)
20	Heritage Park	L. Benches	A. No accessible route to one bench in this area	Dogwood Path Bench After Bridge by 9/11 Memorial	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to at least one bench in this area. (Cost estimate for a 10' long by 4' wide stone dust walkway.)	1	\$320			
21	Heritage Park	L. Benches	A. No accessible route to one bench in this area	Dogwood Path Bench Before Bridge by Concord Road	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to at least one bench in this area. (Cost estimate for a 6' long by 4' wide stone dust walkway.)	1	\$192			
22	Heritage Park	L. Benches	A. No accessible route to one bench in this area	Walkway from 9/11 Memorial to Pond	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to at least one bench in this area. (Cost estimate for a 6' long by 4' wide stone dust walkway.)	1	\$192			
23	Heritage Park	L. Benches	A. No accessible route to one bench in this area	Walkway from Old Sudbury Road to 9/11 Memorial	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to at least one bench in this area. (Cost estimate for a 10' long by 4' wide stone dust walkway.)	1	\$320			
24	Heritage Park	L. Benches	A. No accessible route to one bench in this area	Walkway South of Pond	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to at least one bench in this area. (Cost estimate for a 6' long by 4' wide stone dust walkway.)	1	\$192			
25	Heritage Park	L. Benches	A. No accessible route to one bench in this area	Walkway South of Pond	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to at least one bench in this area. (Cost estimate for 10' long 4' wide stone dust walkway.)	1	\$320			
26	Heritage Park	N/A	N/A	9/11 Memorial	Exterior	N/A	Priority 4	Enhanced Usability	Recommend providing space alongside one bench in each area for a wheelchair user to sit shoulder to shoulder with a person seated on the bench.	1	\$0			
27	Heritage Park	N/A	N/A	Main Entrance from Old Sudbury Road	Exterior	N/A	Priority 4	Enhanced Usability	Recommend providing visual contrast strips at stair for safety and increased visibility.	1	\$0			
28	Heritage Park	N/A	N/A	Main Entrance from Old Sudbury Road	Exterior	N/A	Priority 4	Enhanced Usability	Recommend providing an accessible entrance to the park at this point if possible.	1	\$0			
29	Heritage Park	N/A	N/A	Near Pond	Exterior	N/A	Priority 4	Enhanced Usability	Recommend providing a 48" wide route around all sides of one picnic table in each area.	1	\$0			
1	Playground at 59 Horse Pond Road	A. Exterior Access Route	C. Exterior route < 48" wide G. Cross slope > 1:50 (2.00%) H. Running slope > 1:20 (5%) M. Route not maintained in operable working condition	Route from East End of Wilshire Road	Exterior	N/A	Priority 1	Program Access	Provide an accessible route to the field from Wilshire Road. (Cost estimate for a 100' long, 4' wide accessible stone dust route.)	1	\$3,200			
2	Playground at 59 Horse Pond Road	J. Picnic Tables	G. Toe or knee clearance at table not provided H. Picnic table not on an accessible route	Sunny Picnic Area	Exterior	N/A	Priority 1	Program Access	Provide at least one picnic table with top between 28"- 34" above the ground and 27" clear height underneath. Ensure that the picnic table is connected to an accessible route. (Cost estimate for a 130' long, 4' wide stone dust route and an accessible picnic table.)	1	\$5,560			
3	Playground at 59 Horse Pond Road	C. Field	A. Accessible spaces are not provided at team seating C. Not connected to an accessible-route	East Team Seating Area	Exterior	N/A	Priority 1	Program Access	Provide a 36" x 48" clear floor space at team seating alongside the bench. Provide an accessible route to the team seating area. (Cost estimate for a 36" by 48" stone dust clear floor space alongside the bench and a 30' long, 4' wide accessible stone dust route from the edge of the field to the team seating area.)	1	\$1,056			
4	Playground at 59 Horse Pond Road	C. Field	A. Accessible spaces are not provided at team seating C. Not connected to an accessible-route	West Team Seating Area	Exterior	N/A	Priority 1	Program Access	Provide a 36" x 48" clear floor space at team seating. Provide an accessible route to the team seating area. (Cost estimate for a 36" by 48" stone dust clear floor space alongside the bench and a 30' long, 4' wide accessible stone dust route from the spectator seating area to the west team seating area.)	1	\$1,152			

Information Provided by Institute for Human Centered Design										Status of Barrier Removal				
ID	Facility Name	Element	Issue/Physical Barrier	Location	Floor	Room	Town Priority	Priority for Barrier Removal	Remedies	Quantity	Estimated Cost of Barrier Removal	Barrier Removal Complete (Y/N)	Completion Date (Month/Year)	Completion Date (Fiscal Year)
5	Playground at 59 Horse Pond Road	C. Field	B. Accessible spaces not provided at sidelines seating C. Not connected to an accessible-route	Spectator Seating Area	Exterior	N/A	Priority 1	Program Access	Provide a 36" x 48" clear floor space at sidelines seating. Provide an accessible route to the the spectator seating area. (Cost estimate for a 36" by 48" stone dust clear floor space alongside the bench and an 26' long, 4' wide accessible stone dust route from the east team seating area to the spectator seating area.)	1	\$928			
6	Playground at 59 Horse Pond Road	N/A	N/A	Sunny Picnic Area	Exterior	N/A	Priority 4	Enhanced Usability	Recommend providing a 48" wide min. stable, firm and slip resistant surface under and around an accessible picnic table.	1	\$0			
1	Ti-Sales Field	E. Off-Street Parking Lot or Garage	A. Total # of parking B. Total # of designated accessible parking spaces	Parking Lot	Exterior	N/A	Priority 1	Program Access	Based on 112 estimated parking spaces, provide four (4) car accessible parking spaces and one (1) van accessible parking space.	5	\$4,000			
2	Ti-Sales Field	A. Exterior Access Route	N. Accessible route not provided	Route from Parking Lot to Field	Exterior	N/A	Priority 1	Program Access	Ensure an accessible route is provided. (Cost estimate for a 70' long, 4' wide stone dust route.)	1	\$2,240			
1	Willis Lake Access	A. Exterior Access Route	A. Not provided from all site arrival points	Wayside Near Picnic Area and Dock	Exterior	N/A	Priority 1	Program Access	Ensure an accessible route is provided to the wayside.(Relocate picnic table so it does not obstruct access to the clear floor space at the wayside.)	1	\$0			
2	Willis Lake Access	A. Exterior Access Route	H. Running slope > 1:20 (5%)	Path to Memorial	Exterior	N/A	Priority 3	Additional Access	Reduce running slope to be no steeper than 1:20 (5%). (Reducing running slope on path to memorial may be technically infeasible.)	1	\$0			
3	Willis Lake Access	A. Exterior Access Route	J. Level changes > 1/4"	Near Memorial and Exterior Stairs	Exterior	N/A	Priority 3	Additional Access	Alter change in level to be 1/4" high max.	1	\$160			
4	Willis Lake Access	A. Exterior Access Route	J. Level changes > 1/4"	Dock	Exterior	N/A	Priority 3	Additional Access	Alter change in level to be 1/4" high max.	1	\$0			
5	Willis Lake Access	E. Off-Street Parking Lot or Garage	A. Total # of parking B. Total # of designated accessible parking spaces C. Total # of designated van accessible spaces G. Access aisle not provided N. Sign not provided O. Sign does not have the designation "Van Accessible"	Parking Area Near Dock	Exterior	N/A	Priority 1	Program Access	Provide a compliant van accessible parking space with a marked access aisle 60" wide min. and no steeper than 1:48 (2.08%) in all directions. Provide a sign with the International Symbol of Accessibility (ISA) located 60" min. and 96" max. above the ground. Add the designation "Van Accessible" to the sign located at the van accessible space.	1	\$1,850			
6	Willis Lake Access	J. Picnic Tables	G. Toe or knee clearance at table not provided	Picnic Area by Dock	Exterior	N/A	Priority 1	Program Access	Provide at least one picnic table with top between 28" - 34" above the ground and 27" clear height underneath.	1	\$1,400			
7	Willis Lake Access	Memorial	N/A	Memorial	Exterior	N/A	Priority 4	Enhanced Usability	Recommend, since providing an accessible route to the memorial may be technically infeasible, including some photos and descriptions of the memorial at the wayside by the beach so individuals who are unable to access the memorial can see and learn about it.	1	\$0			
8	Willis Lake Access	Picnic Table	N/A	Picnic Area by Dock	Exterior	N/A	Priority 4	Enhanced Usability	Recommend providing a 48" wide min. stable, firm and slip resistant surface such as stone dust under and around an accessible picnic table once one is placed in the picnic area by the dock.	1	\$0			
9	Willis Lake Access	Sign	N/A	Lake Shore Drive	Exterior	N/A	Priority 4	Enhanced Usability	Recommend providing a sign at the intersection of Lake Shore Drive and Elmwood Avenue directing visitors to Willis Lake Park.	1	\$0			