Field Report No. 10	page
---------------------	------

	Client:			Town of Sudbury
	Project Name:		Sudbury-Hudso	n Transmission Reliability
	Inspector:			Jeffrey Polidor
	Project No:			22012F
Lardov Witton	Inspection Date:	5/24/23	Arrival Time:	12:00 PM
Horsley Witten Group, Inc.	Weather:	Sunny, 75°F	<b>Departure Time:</b>	3:00 PM

Personnel on site:

Marc Bergeron Matt Lagoy

Terry Ramborger

Contractor(s) equipment:

Excavator (2) Dumpster (1) **Reference Plan:** 

Sudbury to Hudson

115kV Underground Transmission Line

1

Sudbury - Hudson, MA Date: November 16, 2018

#### **WORK UNDERWAY:**

Erosion Control Installation	$\boxtimes$
Clearing/Grubbing	
Excavation/Fill/Compaction	
Road Subbase Installation	
Gravel Base Installation	
Pavement/Binder Installation	
Water Installation	
Gas/Electric/Telephone	
Installation	

Drainage Installation	
Wastewater Construction	
Sidewalk Construction	
Final Grading	
Surface Stabilization	
Monument Installation	
Cleanup	
Other:	

Phone: (508) 833-6600

Phone: (857) 263-8193

Phone: (401) 272-1717

Phone: (603) 658-1660

Photos Taken: Yes No

### **General Notes/Comments:**

On May 24, 2023, Horsley Witten Group, Inc. (HW) performed a site visit along the Eversource transmission line corridor in Sudbury, MA. During the site visit HW walked all segments with erosion control installed (7-14) and confirmed erosion control practices at the gravel construction entrances are still in working condition.

- Silt fence and filter tube are functioning properly along segments 14, 12, 11, 10, 8, and 7 (Photos 1, 4, 5, 6, 9, and 10).
- Silt fence is sagging in one location and lifted above the ground in a second location along segment 13 near Hop Brook Bridge (Photos 2-3).
- Construction entrance at STA 407+50 has visible sediment tracking into the road (Photo 7).
- Silt fence has a broken stake along segment 9 (Photo 8).

#### **Action Items:**

1. Repair silt fence and filter tube as noted above.

2. Add stones to the construction entrance at STA 407+50.

Inspector's signature:

Date: 5/24/23

Jeffrey Polidor

Survey-GIS Technician

**Distribution:** 

Town: Lori Capone

Shawna Risotti

Epsilon Associates: Marc Bergeron
Horsley Witten Group: Janet Carter Bernardo, P.E.

Jeffrey Polidor

caponel@sudbury.ma.us RisottiS@sudbury.ma.us

 $mberger on @\, epsilon associates. com$ 

Phone: (508) 833-6600

Phone: (857) 263-8193

Phone: (401) 272-1717

Phone: (603) 658-1660

jbernardo@horsleywitten.com jolidor@horsleywitten.com

## **PHOTOS:**



**Photo 1:** Silt fence and filter tube functioning properly along segment 14. Photo taken on 5/24/23

# Horsley Witten Group, Inc.



**Photo 2:** Broken stake in the silt fence along segment 13 near Hop Brook Bridge. Photo taken on 5/24/23



**Photo 3:** Debris accumulating and lifting of silt fence along segment 13 near Hop Brook Bridge. Photo taken on 5/24/23

Phone: (508) 833-6600

Phone: (857) 263-8193

Phone: (401) 272-1717



**Photo 4:** Silt fence functioning properly along segment 12. Photo taken on 5/24/23



Phone: (508) 833-6600

Phone: (857) 263-8193

Phone: (401) 272-1717

**Photo 5:** Silt fence functioning properly along segment 11. Photo taken on 5/24/23



**Photo 6:** Silt fence functioning properly along segment 10. Photo taken on 5/24/23



**Photo 7:** Construction entrance at STA 407+50 has visible sediment tracking onto the road. Photo taken on 5/24/23

Phone: (508) 833-6600

Phone: (857) 263-8193

Phone: (401) 272-1717



**Photo 8:** Broken stake in the silt fence along segment 9. Photo taken on 5/24/23



Phone: (508) 833-6600

Phone: (857) 263-8193

Phone: (401) 272-1717

**Photo 9:** Silt fence functioning properly along segment 8. Photo taken on 5/24/23



Phone: (508) 833-6600

Phone: (857) 263-8193

Phone: (401) 272-1717

**Photo 10:** Silt fence functioning properly along segment 7. Photo taken on 5/24/23