

Horsley Witten Group, Inc.

Client:			Town of Sudbury
Project Name:		Sudbury-Hudso	on Transmission Reliability
Inspector:			Jeffrey Polidor
Project No:			<u>22012F</u>
Inspection Date:	6/15/23	Arrival Time:	11:00 AM
Weather:	Sunny, 70°F	Departure Time:	

## Personnel on site:

Marc Bergeron Matt Lagoy **Terry Ramborger** 

# **Reference Plan:**

Sudbury to Hudson 115kV Underground Transmission Line Sudbury - Hudson, MA Date: November 16, 2018

## **Contractor(s) equipment:**

Excavator (2) Dumpster (1)

### WORK UNDERWAY:

Erosion Control Installation	$\square$
Clearing/Grubbing	
Excavation/Fill/Compaction	
Road Subbase Installation	
Gravel Base Installation	
Pavement/Binder Installation	
Water Installation	
Gas/Electric/Telephone	
Installation	

Drainage Installation	$\square$
Wastewater Construction	
Sidewalk Construction	
Final Grading	
Surface Stabilization	
Monument Installation	
Cleanup	
Other:	

Photos Taken: Yes 🔀 No 🗌

#### **General Notes/Comments:**

On June 15, 2023, Horsley Witten Group, Inc. (HW) performed a site visit along the Eversource transmission line corridor in Sudbury, MA. During the site visit HW walked all segments with erosion control installed (7-14) and confirmed erosion control practices at the gravel construction entrances are still in working condition.

- Silt fence and filter tube are functioning properly along segments 14, 13, 11, 10, and 9 (Photos 1, 4, 6, 7, and 8).
- Trash was noted beside standing water on segment 14 (Photo 2). •
- An electrical manhole was being installed along segment 14 (Photo 3).
- Silt fence and filter tube was sagging along segment 12 (Photo 5). ٠
- Silt fence is ripped along segment 8 (Photo 9).
- Debris pile up is lifting the silt fence along segment 8 near Hop Brook Bridge (Photo 10).
- Silt fence has a broken stake along segment 7 near Hop Brook Bridge (Photo 11).

#### **Action Items:**

- 1. Repair silt fence and filter tube as noted above.
- 2. Clean garbage along segment 14.

roy /oh

Inspector's signature:

Jeffrey Polidor Survey-GIS Technician Date: 6/15/23

#### **Distribution:** Town:

Epsilon Associates: Horsley Witten Group: Lori Capone Shawna Risotti Marc Bergeron Janet Carter Bernardo, P.E. Jeffrey Polidor caponel@sudbury.ma.us RisottiS@sudbury.ma.us mbergeron@epsilonassociates.com jbernardo@horsleywitten.com jolidor@horsleywitten.com

#### PHOTOS:



**Photo 1:** Silt fence and filter tube functioning properly along segment 14 near Hop Brook Bridge. Photo taken on 6/15/23

Horsley Witten Group, Inc. 90 Route 6A, Sandwich, MA 02563 112 Water Street, 6<sup>th</sup> Floor, Boston, MA 02109 One Turks Head, Suite 300, Providence, RI 02903 113 R2 Water Street, Exeter, NH, 03833



**Photo 2:** Trash next to standing water along segment 14. Photo taken on 6/15/23



**Photo 3:** Manhole being installed along segment 14. Photo taken on 6/15/23

Horsley Witten Group, Inc. 90 Route 6A, Sandwich, MA 02563 112 Water Street, 6<sup>th</sup> Floor, Boston, MA 02109 One Turks Head, Suite 300, Providence, RI 02903 113 R2 Water Street, Exeter, NH, 03833



**Photo 4:** Silt fence and filter tube functioning properly next to installed culvert along segment 13. Photo taken on 6/15/23



**Photo 5:** Silt fence and filter tube sagging along segment 12. Photo taken on 6/15/23



**Photo 6:** Silt fence functioning properly along segment 11. Photo taken on 6/15/23



**Photo 7:** Silt fence functioning properly along segment 10. Photo taken on 6/15/23



**Photo 8:** Silt fence functioning properly along segment 9. Photo taken on 6/15/23



**Photo 9:** Rip in the silt fence along segment 8. Photo taken on 6/15/23



**Photo 10:** Debris pile up in the silt fence along segment 8 near Hop Brook Bridge. Photo taken on 6/15/23



**Photo 11:** Broken stake in the silt fence along segment 7 near Hop Brook Bridge. Photo taken on 6/15/23