Field	Report	No.	14
-------	--------	-----	----

•				
	Client:			Town of Sudbury
	Project Name:	Sudbury-Hudson Transmission Reliability		
	Inspector:			Jeffrey Polidor
	Project No:			22012F
Horsley Witten	Inspection Date:	9/06/23	Arrival Time:	8:00 AM
Group, Inc.	Weather:	Sunny, 85°F	Departure Time:	11:30 AM

Contractor(s) equipment:

Excavator (2) Dumpster (2)

Dumpster (2) Roller (1)

## **Reference Plan:**

Sudbury to Hudson

115kV Underground Transmission Line

Sudbury - Hudson, MA Date: November 16, 2018

### **WORK UNDERWAY:**

Erosion Control Installation	
	$\boxtimes$
Clearing/Grubbing	
Excavation/Fill/Compaction	$\boxtimes$
Road Subbase Installation	
Gravel Base Installation	
Pavement/Binder Installation	
Water Installation	
Gas/Electric/Telephone	
Installation	

Drainage Installation	$\boxtimes$
Wastewater Construction	
Sidewalk Construction	
Final Grading	
Surface Stabilization	
Monument Installation	
Cleanup	
Other:	

Phone: (508) 833-6600

Phone: (857) 263-8193

Phone: (401) 272-1717

Phone: (603) 658-1660

Photos Taken: Yes No

# **General Notes/Comments:**

On September 6, 2023, Horsley Witten Group, Inc. (HW) performed a site visit along the Eversource transmission line corridor in Sudbury, MA. During the site visit HW walked all segments with erosion control installed (7-14) and confirmed erosion control practices at the gravel construction entrances are still in working condition.

- Silt fence and filter tube are functioning properly along segments 7-9, 12, and 14.
- A manhole was being installed in between segment 8 and segment 9 (Photo 1)
- Silt fence has a broken stake along segment 10 (Photo 2).
- Sediment has tracked into the road from gravel construction entrance STA 361+00 (Photo 3).
- Silt fence has a broken stake along segment 11 in two places (Photo 3).
- Silt fence is under a boulder at a point along segment 13 (Photo 4).
- Silt fence has a broken stake at Bridge 127 along segment 13 (Photo 5)
- Form, rebar, and pour abutment wall was being installed at Bridge 127 (Photo 6).

## **Action Items:**

**1.** Repair silt fence and filter tube as noted above.

Field Report No. 14 page 2

Inspector's signature:

Date: 9/6/23

Jeffrey Polidor

Survey-GIS Technician

**Distribution:** 

Town: Lori Capone

Shawna Risotti

Epsilon Associates: Marc Bergeron
Horsley Witten Group: Janet Carter Bernardo, P.E.

Jeffrey Polidor

caponel@sudbury.ma.us RisottiS@sudbury.ma.us

mbergeron@epsilonassociates.com

Phone: (508) 833-6600

Phone: (857) 263-8193

Phone: (401) 272-1717

Phone: (603) 658-1660

jbernardo@horsleywitten.com jolidor@horsleywitten.com

### **PHOTOS:**



**Photo 1:** Manhole installation between segment 8 and segment 9. Photo taken on 9/06/23

Field Report No. 14



page 3

Phone: (508) 833-6600

Phone: (857) 263-8193

Phone: (401) 272-1717

Phone: (603) 658-1660

**Photo 2:** Broken stake in the silt fence along segment 10. Photo taken on 9/06/23



**Photo 3:** Sediment in the road from gravel construction entrance STA 361+00. Photo taken on 9/06/23

Field Report No. 14

Phone: (508) 833-6600

Phone: (857) 263-8193 Phone: (401) 272-1717

Phone: (603) 658-1660



**Photo 4:** Boulder on the silt fence along segment 13. Photo taken on 9/06/23



**Photo 5:** Broken stake in the silt fence near Bridge 127 along segment 13. Photo taken on 9/06/23

Field Report No. 14

Phone: (508) 833-6600

Phone: (857) 263-8193

Phone: (401) 272-1717

Phone: (603) 658-1660



**Photo 6:** Form, rebar, and pour abutment wall being installed at Bridge 127. Photo taken on 9/06/23