Field	l Rep	ort	No.	17
-------	-------	-----	-----	----

page 1

	Client:		Town of Sudbury		
	Project Name:	Sudbury-Hudson Transmission Reliability			
	Inspector:		Jeffrey Polidor		
	Project No:		22012F		
Horsley Witten	Inspection Date:	10/23/23 Arrival Time:	8:00 AM		
Group, Inc.	Weather:	Clear, 50°F Departure Time:	11:30 AM		
Contractor(s)	equipment:	Reference Plan:			

Excavator (2) Dumpster (2) Roller (1) Sudbury to Hudson

115kV Underground Transmission Line Sudbury - Hudson, MA

Date: November 16, 2018

WORK UNDERWAY:

Erosion Control Installation	\boxtimes
Clearing/Grubbing	
Excavation/Fill/Compaction	\boxtimes
Road Subbase Installation	
Gravel Base Installation	
Pavement/Binder Installation	
Water Installation	
Gas/Electric/Telephone	\boxtimes
Installation	

Drainage Installation	
Wastewater Construction	
Sidewalk Construction	
Final Grading	
Surface Stabilization	
Monument Installation	
Cleanup	
Other:	

Phone: (508) 833-6600

Phone: (857) 263-8193

Phone: (401) 272-1717 Phone: (603) 658-1660

Photos Taken: Yes No

General Notes/Comments:

On October 23, 2023, Horsley Witten Group, Inc. (HW) performed a site visit along the Eversource transmission line corridor in Sudbury, MA. During the site visit HW walked all segments with erosion control installed (7-14) and confirmed erosion control practices at the gravel construction entrances are still in working condition.

- Silt fence and filter tube are functioning properly along segments 7 and 11-14.
- Bridge 128 is closed (Photo 1).
- Silt fence is ripped in two places along segment 8 (Photo 2).
- Silt fence is ripped along segment 9.
- Drainage pipes have been delivered along segment 10 and are awaiting structure installation (Photo 3).
- Silt fence has broken stakes in two places along segment 10 (Photo 4).
- Sediment is tracked into the road at construction entrance STA 407+50 (Photo 5).
- Cut and fill was being done along segment 11 (Photo 6).

Action Items:

- 1. Repair silt fence as noted above.
- 2. Clear sediment from the street at construction entrance STA 407+50.

Horsley Witten Group, Inc.

Field Report No. 17 page 2

Inspector's signature:

Jeffrey Polidor Survey-GIS Technician Date: 10/23/23

Distribution:

Town: Lori Capone Shawna Risotti

Epsilon Associates: Marc Bergeron
Horsley Witten Group: Janet Carter Bernardo, P.E.

Jeffrey Polidor

caponel@sudbury.ma.us RisottiS@sudbury.ma.us

mbergeron@epsilonassociates.com jbernardo@horsleywitten.com jolidor@horsleywitten.com

> Phone: (508) 833-6600 Phone: (857) 263-8193

> Phone: (401) 272-1717

Phone: (603) 658-1660

PHOTOS:



Photo 1: Bridge 128 closed. Photo taken on 10/23/23

Field Report No. 17 page 3



Photo 2: Rip in the silt fence in standing water along segment 8. Photo taken on 10/23/23



Phone: (508) 833-6600

Phone: (857) 263-8193 Phone: (401) 272-1717

Phone: (603) 658-1660

Photo 3: Drainage pipes along segment 10 waiting for structure installation. Photo taken on 10/23/23

Field Report No. 17

Phone: (508) 833-6600

Phone: (857) 263-8193 Phone: (401) 272-1717

Phone: (603) 658-1660



Photo 4: Broken stakes in the silt fence along segment 10. Photo taken on 10/23/23



Photo 5: Sediment tracked into the road at construction entrance STA 407+50. Photo taken on 10/23/23

Field Report No. 17 page 5



Phone: (508) 833-6600

Phone: (857) 263-8193 Phone: (401) 272-1717

Phone: (603) 658-1660

Photo 6: Earthwork activity along segment 11. Photo taken on 10/23/23