



Horsley Witten Group, Inc.

Client:..... Town of Sudbury
 Project Name:..... Sudbury-Hudson Transmission Reliability
 Inspector:..... Jeffrey Polidor
 Project No:..... 22012F
 Inspection Date:..... 1/28/25 Arrival Time:..... 9:30 AM
 Weather:..... Flurries, 25°F Departure Time:..... 12:30 PM

Contractor(s) equipment:

None at time of visit

Reference Plan:

Sudbury to Hudson
 115kV Underground Transmission Line
 Sudbury - Hudson, MA
 Date: November 16, 2018

WORK UNDERWAY:

| | |
|-------------------------------------|-------------------------------------|
| Erosion Control Installation | <input checked="" type="checkbox"/> |
| Clearing/Grubbing | <input type="checkbox"/> |
| Excavation/Fill/Compaction | <input type="checkbox"/> |
| Road Subbase Installation | <input type="checkbox"/> |
| Gravel Base Installation | <input type="checkbox"/> |
| Pavement/Binder Installation | <input type="checkbox"/> |
| Water Installation | <input type="checkbox"/> |
| Gas/Electric/Telephone Installation | <input type="checkbox"/> |

| | |
|-------------------------|--------------------------|
| Drainage Installation | <input type="checkbox"/> |
| Wastewater Construction | <input type="checkbox"/> |
| Sidewalk Construction | <input type="checkbox"/> |
| Final Grading | <input type="checkbox"/> |
| Surface Stabilization | <input type="checkbox"/> |
| Monument Installation | <input type="checkbox"/> |
| Cleanup | <input type="checkbox"/> |
| Other: | <input type="checkbox"/> |

Photos Taken: Yes No

General Notes/Comments:

On January 28, 2025, Horsley Witten Group, Inc. (HW) staff performed a site visit along the Eversource Transmission Line corridor in Sudbury, MA. During the site visit HW walked all segments with erosion controls installed (7-14) and confirmed erosion control practices at the gravel construction entrances are still in working condition.

- Silt fence and filter tube are functioning properly along segments 10 and 12-13.
- Rip in the silt fence at a trail connection along segment 7 (Photo 1).
- Plantings along Hop Brook Bridge (Photo 2).
- Silt fence is ripped from stake along segment 8 (Photo 3).
- Silt fence is ripped from stake along segment 9 (Photo 4).
- Rip in the silt fence along segment 11 (Photo 5).
- Broken Stake in the silt fence along segment 14 (Photo 6).

Action Items:

1. Repair silt fence as noted above prior to initiating next phase of construction.

Horsley Witten Group, Inc.

90 Route 6A, Sandwich, MA 02563
 112 Water Street, 6th Floor, Boston, MA 02109
 One Turks Head Place, Suite 300, Providence, RI 02903
 113 R2 Water Street, Exeter, NH, 03833

Phone: (508) 833-6600
 Phone: (857) 263-8193
 Phone: (401) 272-1717
 Phone: (603) 658-1660

Inspector's signature: Jeffrey Polidor

Date: 1/28/25

Jeffrey Polidor
Survey-GIS Technician

Distribution:

| | | |
|-----------------------|-----------------------------|---------------------------------|
| Town: | Lori Capone | caponel@sudbury.ma.us |
| | Shawna Risotti | RisottiS@sudbury.ma.us |
| | Adam Burney | burneya@sudbury.ma.us |
| Epsilon Associates: | Marc Bergeron | mbergeron@epsilonassociates.com |
| Horsley Witten Group: | Janet Carter Bernardo, P.E. | jbernardo@horsleywitten.com |
| | Jeffrey Polidor | jolidor@horsleywitten.com |

PHOTOS:



Photo 1: Rip in the silt fence at a trail connection along segment 7.
Photo taken on 1/28/25

Horsley Witten Group, Inc.

90 Route 6A, Sandwich, MA 02563
112 Water Street, 6th Floor, Boston, MA 02109
One Turks Head Place, Suite 300, Providence, RI 02903
113 R2 Water Street, Exeter, NH, 03833

Phone: (508) 833-6600
Phone: (857) 263-8193
Phone: (401) 272-1717
Phone: (603) 658-1660



Photo 2: Plantings along Hop Brook Bridge.
Photo taken on 1/28/25



Photo 3: Silt fence is ripped from stake along segment 8.
Photo taken on 1/28/25

Horsley Witten Group, Inc.

90 Route 6A, Sandwich, MA 02563
112 Water Street, 6th Floor, Boston, MA 02109
One Turks Head Place, Suite 300, Providence, RI 02903
113 R2 Water Street, Exeter, NH, 03833

Phone: (508) 833-6600
Phone: (857) 263-8193
Phone: (401) 272-1717
Phone: (603) 658-1660



Photo 4: Silt fence is ripped from stake along segment 9.
Photo taken on 1/28/25



Photo 5: Rip in the silt fence along segment 11.
Photo taken on 1/28/25.

Horsley Witten Group, Inc.

90 Route 6A, Sandwich, MA 02563
112 Water Street, 6th Floor, Boston, MA 02109
One Turks Head Place, Suite 300, Providence, RI 02903
113 R2 Water Street, Exeter, NH, 03833

Phone: (508) 833-6600
Phone: (857) 263-8193
Phone: (401) 272-1717
Phone: (603) 658-1660



Photo 6: Broken Stake in the silt fence along segment 14.
Photo taken on 1/28/25.

Horsley Witten Group, Inc.

90 Route 6A, Sandwich, MA 02563
112 Water Street, 6th Floor, Boston, MA 02109
One Turks Head Place, Suite 300, Providence, RI 02903
113 R2 Water Street, Exeter, NH, 03833

Phone: (508) 833-6600
Phone: (857) 263-8193
Phone: (401) 272-1717
Phone: (603) 658-1660