

Horsley Witten Group, Inc.

Client:			Town of Sudbury
Project Name:		Sudbury-Hudsor	Transmission Reliability
Inspector:			Jeffrey Polidor
Project No:			<u>22012F</u>
Inspection Date:	10/15/24	Arrival Time:	<u>9:00 AM</u>
Weather:	Clear, 50°F De	eparture Time:	12:00 PM

Contractor(s) equipment: Watering Truck (1) Vacuum Truck (1) Reference Plan: Sudbury to Hudson 115kV Underground Transmission Line Sudbury - Hudson, MA Date: November 16, 2018

WORK UNDERWAY:

Erosion Control Installation	\square
Clearing/Grubbing	
Excavation/Fill/Compaction	
Road Subbase Installation	
Gravel Base Installation	
Pavement/Binder Installation	
Water Installation	
Gas/Electric/Telephone	
Installation	

Drainage Installation	\square
Wastewater Construction	
Sidewalk Construction	
Final Grading	
Surface Stabilization	
Monument Installation	
Cleanup	
Other:	

Photos Taken: Yes 🔀 No 🗌

General Notes/Comments:

On October 15, 2024, Horsley Witten Group, Inc. (HW) staff performed a site visit along the Eversource Transmission Line corridor in Sudbury, MA. During the site visit HW walked all segments with erosion controls installed (7-14) and confirmed erosion control practices at the gravel construction entrances are still in working condition.

- Silt fence and filter tube are functioning properly along segments 9-14.
- Broken stakes in the silt fence along segment 7 (Photo 1).
- Broken stakes in the silt fence along segment 8 (Photo 2).
- New plantings next to bridge 128 (Photo 3).
- Vacuum truck clearing culverts along segment 9 (Photo 4).
- New plantings watered along segment 11 (Photo 5).
- New plantings at bridge 127 (Photo 6).

Action Items:

1. Repair silt fence and filter tube as noted above.

nay Poly

Date: 10/15/24

Inspector's signature:

Jeffrey Polidor Survey-GIS Technician

Distribution:

Town:

Epsilon Associates: Horsley Witten Group: Lori Capone Shawna Risotti Adam Burney Marc Bergeron Janet Carter Bernardo, P.E. Jeffrey Polidor

caponel@sudbury.ma.us RisottiS@sudbury.ma.us burneya@sudbury.ma.us mbergeron@epsilonassociates.com jbernardo@horsleywitten.com jolidor@horsleywitten.com

PHOTOS:



Photo 1: Broken stakes in the silt fence along segment 7. Photo taken on 10/15/24

Horsley Witten Group, Inc. 90 Route 6A, Sandwich, MA 02563 112 Water Street, 6th Floor, Boston, MA 02109 One Turks Head Place, Suite 300, Providence, RI 02903 113 R2 Water Street, Exeter, NH, 03833



Photo 2: Broken stakes in the silt fence along segment 8. Photo taken on 10/15/24



Photo 3: New plantings at Bridge 128. Photo taken on 10/15/24

Horsley Witten Group, Inc. 90 Route 6A, Sandwich, MA 02563 112 Water Street, 6th Floor, Boston, MA 02109 One Turks Head Place, Suite 300, Providence, RI 02903 113 R2 Water Street, Exeter, NH, 03833



Photo 4: Vacuum truck clearing culverts along segment 9. Photo taken on 10/15/24



Photo 5: New plantings watered along segment 11. Photo taken on 10/15/24.

Horsley Witten Group, Inc. 90 Route 6A, Sandwich, MA 02563 112 Water Street, 6th Floor, Boston, MA 02109 One Turks Head Place, Suite 300, Providence, RI 02903 113 R2 Water Street, Exeter, NH, 03833



Photo 6: New plantings at Bridge 127. Photo taken on 10/15/24.