

### Field Inspection Report #13

Project Name:	Bruce Freeman Rail Trail	Submitted to:	Marcia Rasmussen, Planning Development Assistant		
Inspection Date:	12/22/2023	Project Address:	Sudbury, MA		
F&O Project #:	20200785.C10	City:	Sudbury	State:	MA
MassDOT Project #	608164	Client:	Town of Sudbury		
		Photos Included:	10 photos		

Date/Inspector(s)/Time:	12/22/2023 Benjamin Andersen 9:00 PM – 12:30 PM
-------------------------	---

#### **Site Observations:**

- F&O visited the project site and walked the length of the project.
- Groups on site:
  - A.A Will Corporation
- The following observations were made:

#### **Between Sta 101+00 and 116+00 (Project start to Codjer Lane)**

- Timber fencing has been constructed. (See Photo 1)

#### **Between Sta 116+00 and 143+00 (Codjer Lane to Old Lancaster Road)**

- Timber fencing has been constructed.

#### **Between Sta 143+00 and 175+00 (Old Lancaster Road to Hudson Road)**

- Timber fencing has been constructed.
- Timber fencing across the culvert at Station 167+00 has been added. (See Photo 2)

#### **Between Sta. 175+00 and 215+80 (Hudson Road to Morse Road)**

- The Parkinson's Lot spur path has been paved. (See Photo 3)
- Loam and seed have been added to the side slopes of the Parkinson's Lot spur path.
- Portions of timber fencing have been constructed and the contractor was working on installing more fencing during the visit. (See Photo 4)
- Proposed vegetation has been planted near the wetland replication area south of Morse Road. (See Photo 5)

#### **Between Sta. 215+80 and 275+00 (Morse Road to Haynes Road)**

- This portion of the project has been paved since the previous site visit in November. (See Photo 6)
- The Pantry Brook bridge has been constructed. (See Photo 7)

- The contractor was working on side slope grading during the visit.

**Between Sta. 275+00 and 284+50 (Haynes Road to Pantry Road)**

- This portion of the project has been paved since the previous site visit in November. (See Photo 8)
- The Davis Field spur path has been paved and the proposed guardrail along North Road has been constructed. (See Photo 9)

**Between Sta. 284+50 and 335+50 (Pantry Road to Project End)**

- Portions of timber fencing have been constructed and the contractor was working on installing more fencing during the visit. (See Photo 10)

Site Photographs:



**Photo 1:** Sta. 104+50 looking north at the timber fencing.



**Photo 2:** Sta. 167+50 looking south at the timber fencing across the 48" culvert.



**Photo 3:** Sta. 184+50 looking west at the Parkinson's Lot spur path.



**Photo 4:** Sta. 185+00 looking north at the timber fencing.





**Photo 5:** Sta. 212+00 looking at the planted vegetation near the wetland replication area.



**Photo 6:** Sta. 234+00 looking south at the paved path and vehicle turnaround.



**Photo 7:** Sta. 164+50 looking at the newly constructed Pantry Brook bridge.



**Photo 8:** Sta. 283+00 looking north at Pantry Road.





**Photo 9:** Sta. 1104+00 looking west at the paved spur path and installed guardrail.



**Photo 10:** Sta. 314+50 looking south at the completed and in construction timber fencing.