

Field Inspection Report #14

Project Name:	Bruce Freeman Rail	Submitted to:		Marcia Rasmussen, Planning			
	Trail			Developme	Development Assistant		
Inspection Date:	02/06/2024	Project Address: Sudbury, MA					
F&O Project #:	20200785.C10	City:	Sudbu	adbury State: MA		MA	
MassDOT Project #	608164	Client: To		wn of Sudbury			
		Photos Included: 12 photos					

	02/06/2024
Date/Inspector(s)/Time:	Benjamin Andersen
	9:00 AM – 12:00 PM

Site Observations:

- F&O visited the project site and walked the length of the project.
- The following observations were made:

Between Sta 101+00 and 116+00 (Project start to Codjer Lane)

- Street name piers were staged next to the trail. (See Photo 1)
- Minimal progress has been made in this section as paving, fencing installation, and side slope grading has been completed.

Between Sta 116+00 and 143+00 (Codjer Lane to Old Lancaster Road)

• Minimal progress has been made in this section as paving, fencing installation, and side slope grading has been completed.

Between Sta 143+00 and 175+00 (Old Lancaster Road to Hudson Road)

• Minimal progress has been made in this section as paving, fencing installation, and side slope grading has been completed.

Between Sta. 175+00 and 215+80 (Hudson Road to Morse Road)

• The remaining fence in this section has been constructed. (See Photo 2)

Between Sta. 215+80 and 275+00 (Morse Road to Haynes Road)

 Minimal progress has been made in this section as paving and side slope grading have been completed.

Between Sta. 275+00 and 284+50 (Haynes Road to Pantry Road)

 Minimal progress has been made in this section as paving and side slope grading have been completed.



Between Sta. 284+50 and 335+50 (Pantry Road to Project End)

- The proposed fencing along the trail adjacent to North Road has been constructed. (See Photo 3)
- All fencing north of North Road has been installed. (See Photo 4)

Note: Photos 5-12 below are additional photos to show the status of the rest of the trail.



Site Photographs:



Photo 1: Proposed granite piers staged before installation.



Photo 2: Sta. 190+00 looking north at the timber fencing.




Photo 3: Sta. 1102+00 looking east at the timber fencing along the Davis Field spur path.



Photo 4: Sta. 321+00 looking north at the timber fencing.





Photo 5: Sta 113+00 looking north towards Codjer Lane.



Photo 6: Sta. 119+50 looking north towards Hop Brook.



Photo 7: Sta. 180+00 looking south away from Hudson Road.



Photo 8: Sta. 181+50 looking north at the proposed rest area location.





Photo 9: Sta. 212+50 looking at the proposed wetland replication area.



Photo 10: Sta. 275+50 looking south across Haynes Road.



Photo 11: Sta. 307+50 standing at North Road looking south at the trail and proposed rest area.



Photo 12: Standing on the Sudbury/Concord town line looking towards Concord.