

Field Inspection Report #8

Project Name:	Bruce Freeman Rail	Submitted to:		Andy Sheehan, Town			
	Trail			Manager	Manager		
Inspection Date:	07/21/2023	Project Address: Sudbury, MA					
F&O Project #:	20200785.C10	City:	Sudbu	Sudbury State: MA		MA	
MassDOT Project #	608164	Client: To		wn of Sudbury			
		Photos I	ncluded	l: 8 photos			

	07/21/2023
Date/Inspector(s)/Time:	Benjamin Andersen
	9:00 AM – 12:00 PM

Site Observations:

- F&O visited the project site and walked the length of the project.
- Groups on site:
 - A.A Will Corporation
- The following observations were made:

Between Sta 101+00 and 116+00 (Project start to Codjer Lane)

• The rest area near the project beginning has been cleared.

Between Sta 116+00 and 143+00 (Codjer Lane to Old Lancaster Road)

• Work has been done to prepare Hop Brook and the surrounding area for the installation of the bridge. (See Photo 1)

Between Sta 143+00 and 175+00 (Old Lancaster Road to Hudson Road)

• The 48" culvert at station 167+00 was functioning well during the visit.

Between Sta. 175+00 and 215+80 (Hudson Road to Morse Road)

- The mast foundation at Hudson Road has been installed. (See Photo 2)
- The spur path at Station 183+50 is currently being used as a staging area for excess soil and other debris. (See Photo 3)
- Grading stakes have been placed along this portion of the trail.
- Gravel has been placed and appears to have been graded in some location towards Morse Road.

Between Sta. 215+80 and 275+00 (Morse Road to Haynes Road)

- Work in the proposed parking lot has continued, including the beginning stages of the detention basin has begun. (See Photo 4)
- Gravel and other materials have been staged in the proposed parking lot area.



- Grading efforts have continued along this portion of the trail.
- The contractor was placing fill in specified areas of need during the visit. (See Photo 5)
- Excavation on the southern side of Pantry Brook has begun. (See Photo 6)
- All ties have been removed from this section.

Between Sta. 275+00 and 284+50 (Haynes Road to Pantry Road)

- Culvert headwall at Station 283+50 has been installed. (See Photo 7)
- The contractor was placing gravel in this section during the visit. (See Photo 8)
- All ties have been removed from this section of the trail.

Between Sta. 284+50 and 335+50 (Pantry Road to Project End)

• Minimal work has been done in this section of the project.

General Notes

- 1. Rail has been removed from the entire length of the project.
- 2. All stacks of rail have been removed from the site.
- 3. Sediment control barriers have been installed throughout the entire length of the project.
- 4. The process of scarification has begun and will happen throughout the entire length of the project.
- 5. All rail ties have been removed from the entire length of the project.



Site Photographs:



Photo 1: Sta. 127+00 looking south at Hop Brook



Photo 2: Sta. 176+00 looking at new signal mast foundation at Hudson Road.



Photo 3: Sta. 184+50 looking north debris staged along the spur path



Photo 4: Looking at the detention basins located in the proposed parking lot along Morse Road





Photo 5: Sta 252+00 looking north at freshly placed fill material



Photo 6: Sta. 265+00 looking south at excavation around Pantry Brook



Photo 7: Sta. 283+50 looking at new headwall near Pantry Road



Photo 8: Sta. 281+00 looking south at new gravel being placed and graded